

# CITY OF ROCKFORD

Steve J. Jazwiec, Mayor Michael F. Young, City Manager

PO Box 561

Rockford, Michigan 49341-0561

T 616-866-1537

F 616-866-6406

www.rockford.mi.us

November 30, 2011

Ms. Nuria Muniz, EPS/NPL Coordinator United States Environmental Protection Agency Region 5 77 W Jackson Blvd Chicago IL 60604-3590

Mr. Joseph Walczak, Senior Project Manager Remediation Division Michigan Department of Environmental Quality PO Box 30473 Lansing MI 48909-7973



Dear Ms. Muniz and Mr. Walczak:

It was a pleasure talking to you and other representatives from the U.S. Environmental Protection Agency (EPA) on Tuesday, November 15, 2011. The following information will summarize our discussions and provide additional information related to the document entitled, Summary of Concerns, as submitted by Ms. Lynn McIntosh, Ms. Gail Mancewicz, and Mr. Grant Medich.

#### INTRODUCTION

As we discussed, the City of Rockford was intimately involved in the planning, predemolition, and demolition phases as part of the redevelopment of the Wolverine World Wide (WWW) tannery site in downtown Rockford. Throughout the petition, numerous claims were made regarding the City's involvement in the redevelopment process. This correspondence will address the concerns raised and provide a perspective on the responsiveness of WWW, the workmanship of the pre-demolition and demolition phases, and compliance to permit requirements that were issued by the City of Rockford.

#### CITY OF ROCKFORD PERMITTING PROCESS

The City of Rockford issued a Demolition Permit through the City Manager's office, as well as a permit through the City's contract building officials, Professional Code Inspection (PCI). The City also issued a Soil Erosion and Sedimentation Control Permit (SESC) prior to demolition, which was extended two (2) separate times during the process. We will address the City's involvement in soil erosion and sedimentation

control monitoring later in this letter. The City conducted daily inspections during the demolition and monitored air quality, noise, soil erosion and sedimentation control measures and stayed in constant communication with WWW and its contractors. This letter will confirm that WWW remained in compliance with all permits issued by the City of Rockford at all times.

#### **ENVIRONMENTAL CONSULTANT**

The City of Rockford engaged the services of Materials Testing Consultants (MTC), a well known and reputable environmental consulting firm in the Grand Rapids area. MTC assigned Mr. Chris Kesner to this project, who provided a variety of services for the City of Rockford. Mr. Kesner reviewed the pre-demolition survey that was conducted by WWW, the Health and Safety Plan, as well as provided review and consultation on the air monitoring data that was submitted to the City by WWW. Mr. Kesner provided consulting services to the City on an as needed basis.

The petitioners have suggested that there were no experienced environmental consultants involved in this project. In addition to Mr. Kesner, we communicated with Mr. Gene Gutting, environmental consultant for Pitsch Companies, with extensive experience and environmental training. As mentioned above, the City issued a separate Soil Erosion and Sedimentation Control Permit and the City of Rockford employs three (3) trained and certified Soil Erosion and Sedimentation Control Officers.

#### **AIR QUALITY**

The petitioner's state, "some wetting and spraying of the buildings did occur..." and suggest that no one was in charge of continuous implementation of the plan. The petition goes on to suggest that air testing and results were inadequate and were never produced directly to the citizens. To the contrary, WWW provided the City of Rockford with daily analytical data from the three (3) air monitoring stations. This information was sent by the City of Rockford directly to the residents. In many cases, the review of air monitoring data by Mr. Kesner accompanied the analytical data that was forwarded directly to the residents. The City of Rockford also required that significant wetting of the site occurred throughout the demolition process, and billed WWW for nearly 500,000 gallons of water that was used during the wetting process. At one point, we received a complaint from the petitioners that there was too much water being put on the site.

#### SOIL EROSION AND SEDIMENTATION CONTROL MONITORING

As mentioned earlier, the City of Rockford issued a standalone Soil Erosion and Sedimentation Control Permit, and provided daily inspection through our three (3) trained and certified inspectors. Adjustments to the Soil Erosion and Sedimentation Control measures were implemented by WWW at the direction of the City. Controls included three (3) rows of silt fence supported by straw bales to filter the storm water that did leave the site. There is no doubt that turbid water did leave the site during

some of the significant rains we experienced during the year, and that is not unusual. WWW contained as much of the storm water on site as they could and pumped the water into a large concrete tank for storage. We believe that WWW was responsive to the City of Rockford's request to modify soil erosion and sedimentation control measures as needed. WWW often contacted the City to review SESC measures during heavy rain events to gain our input. The Michigan Department of Environmental Quality (MDEQ) can confirm the numerous inspections that they conducted on the property, as a result of requests from the petitioners. We are only aware of one (1) incident where the MDEQ requested that corrective actions be taken. Upon notification, WWW promptly made the corrections, as requested by the Department.

#### **CITIZEN INVOLVEMENT**

The City believes strongly in engaging its residents and being responsive to their concerns. Shortly after it was announced that the tannery would be closing, the City held a public forum to gain input from the community. I also personally held numerous meetings with any resident requesting information or wanting to voice concerns on both an individual and group basis. Information was given directly to the residents, including air monitoring results, copies of any and all permits, results of the pre-demolition surveys, results of the Health and Safety Plan, and any information and correspondence that was ever requested by residents from the City.

The petitioners suggest throughout their summary that there was no pre-demolition work conducted and that the demolition occurred in an unplanned and haphazard manner. Being intimately involved in this process from its initiation, we present to the EPA and the Department that the City of Rockford was very involved in the process, conducted consistent monitoring of the demolition, monitored the air monitoring data, Fugitive Dust Plan, wetting of the site, and soil erosion and sedimentation control measures. Information was always shared with the residents at their request and in the end; I would state that the City of Rockford is very pleased with the demolition process and the communication we received from WWW and its consultants.

#### ADDITIONAL INFORMATION

Per our discussion, I have forwarded to you, the test results that were taken on the collected storm water, which was pumped into a large concrete clarifier as a means of controlling storm water runoff. WWW conducted this operation to minimize the surface water that left the site during the large rains we experienced this calendar year. Originally, WWW had contemplated discharging the collected storm water into the City of Rockford's sanitary sewer system for treatment by the North Kent Sewer Authority's clean water plant. Ultimately, WWW used the collected storm water for dust control due to the clean test results.

Also included with this letter are the most recent official laboratory reports of the water sampling done at the City of Rockford's water treatment plant, prior to our new ground water plant being constructed and going online in January of 2000. I have also included

a map showing the proximity of our old water treatment plant that utilized the Rogue River as a public water supply and its downstream relationship to the WWW tannery complex. Finally, I have included a copy of the letter from the Rockford City Council to WWW CEO Blake Krueger expressing the Council's support of the tannery redevelopment to date.

Should you need any additional information, please do not hesitate to contact me and I will continue to provide you information that is helpful to the EPA and your review.

Thank you again for your time and I look forward to talking to you in the near future.

Sincerely,

CITY OF ROCKFORD

Michael F. Young City Manager'

cc: Rockford City Council


David O'Donnell, Michigan Department of Environmental Quality

Drinking Water Laboratory - DWRP Division

3500 N. M.L. King Blvd, Lansing MI 48909

517/335-8184

## **Official Laboratory Report**



Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C1999019189

Customer Number: 73654100

System Name/Owner: Collection Address:

City of Rockford

10 East Bridge, Rockford 49341

Collected By:

**KURT MALZAHN** 

Twp/Sec/Well #:

?/?/?

County: Kent

Collector:

Public Water Supply Operator

Sample Kit #:

36LP

Chlorination: Yes WSSN / Pool ID: 5730

Sampled: 02/22/1999 1:45:00PM

Received: 02/23/1999 03:22PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: WATER PLANT LAB TAP

Site Code:

Supplemental Information Related To Reported Result

Health Minimum Test Result **Analyte Name** Tested Limit MCL Rpt. Limit Test Code NO TESTING - MESSAGE ONLY 03/08/1999 CNONE 19960715 NO TEST

Laboratory Comments and Result Notes:

SAMPLE IMPROPERLY PRESERVED. PH WAS ABOVE LEVEL REQUIRED FOR VALID TESTING. PLEASE RESAMPLE.

Drinking Water Laboratory - DWRP Division

3500 N. M.L. King Blvd, Lansing MI 48909

517/335-8184

## Official Laboratory Report



Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C1999019193 Customer Number: 73654100

Customer rumber. 7505 1100

System Name/Owner: City of Rockford

Collection Address: 10 East Bridge. Rockford 49341

Collected By: KURT MALZAHN

Twp/Sec/Well #: ?/?/?

County: Kent

Collector: Public Water Supply Operator

Sample Kit #: 36NV

Chlorination: Yes

WSSN / Pool ID: 5730

Sampled: 02/22/1999 2:05:00PM

Received: 02/23/1999 03:22PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: WATER PLANT LAB TAP

Site Code:

Supplemental Information Related To Reported Result

Supplemental information Related to Reported Result						
		·	Health	Minimum		
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code	
Not Detected	ALACHLOR	02/25/1999	0.002 mg/L	0.0002  mg/L	CXPT 19960701	
Not Detected	ALDRIN	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	AMETRYN	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	ATRAZINE	02/25/1999	0.003 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	BROMACIL	02/25/1999		$0.002~\mathrm{mg/L}$	CXPT 19960701	
Not Detected	BUTACHLOR	02/25/1999		0.002  mg/L	CXPT 19960701	
Not Detected	BUTYLATE	02/25/1999		0.002 mg/L	CXPT 19960701	
Not Detected	CARBOXIN	02/25/1999		0.002 mg/L	CXPT 19960701	
Not Detected	CHLORDANE.alpha	02/25/1999	0.002 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	CHLORDANE.gamma-	02/25/1999	0.002 mg/L	$0.0002~\mathrm{mg/L}$	CXPT 19960701	
Not Detected	CHLOROTHALONIL	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	CYANAZINE	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	CYCLOATE	02/25/1999		0.002 mg/L	CXPT 19960701	
Not Detected	CYPRAZINE	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	DACTHAL	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	DDD.4.4'-	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	DDE.4.4'-	02/25/1999		0.001 mg/[_	CXPT 19960701	
Not Detected	DDT.4.4'-	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	DIELDRIN	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	DIPHENAMID	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	ENDOSULFAN.alpha	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	ENDOSULFAN.heta	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	ENDRIN	02/25/1999	0.002  mg/L	0.00005  mg/L	CXPT 19960701	
Not Detected	ENDRIN ALDEHYDE	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	EPTAM	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	HEPTACHLOR	02/25/1999	0.0004 mg/L	0.00008 mg/L	CXPT 19960701	
Not Detected	HEPTACHLOR EPOXIDE	02/25/1999	0.0002 mg/L	0.00004 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROBENZENE	02/25/1999	0.001 mg/L	$0.0001~\mathrm{mg/L}$	CXPT 19960701	
Not Detected	HEXACHLOROCYCLOHEXANE (ALPHA-BHC)	02/25/1999		0.001 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROCYCLOHEXANE (BETA-BHC)	02/25/1999		0.001 mg/L	CXPT 19960701	
By authority of F	PA 368 1978 as amended. Process Batch	#: 9030315	1 193 1 03/03	3/1999 11:58:08AM	Page: 1 of 2	

Official Laboratory Report Sample Number: C1999019193

Supplemental	Information	Related To	Reported Result
Supplemental	Illioillianon	INCLARCU I O	Nepolica Nesuli

			Health	Minimum	
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code
Not Detected	HEXACHLOROCYCLOHEXANE (DELTA-BHC)	02/25/1999		0.001 mg/L	CXPT 19960701
Not Detected	HEXACHLOROCYCLOPENTADIENE	02/25/1999	0.05 mg/L	$0.0002~\mathrm{mg/L}$	CXPT 19960701
Not Detected	HEXAZINONE	02/25/1999		0.003 mg/L	CXPT 19960701
Not Detected	LINDANE (GAMMA-BHC)	02/25/1999	0.0002 mg/L	$0.00004~\mathrm{mg/L}$	CXPT 19960701
Not Detected	METHOXYCHLOR	02/25/1999	0.04 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	METOLACHLOR	02/25/1999		0.001 mg/L	CXPT 19960701
Not Detected	METRIBUZIN	02/25/1999		0.001 mg/L	CXPT 19960701
Not Detected	OCTACHLOROCYCLOPENTENE	02/25/1999		0.001 mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1016)	02/25/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1221)	02/25/1999	0.0005 mg/L	0.0002  mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1232)	02/25/1999	0.0005  mg/L	$0.0002~\mathrm{mg/L}$	CXPT 19960701
Not Detected	PCB (AROCLOR 1242)	02/25/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1248)	02/25/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1254)	02/25/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1260)	02/25/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	POLYBROMINATED BIPHENYLS	()2/25/1999		0.001 mg/L	CXPT 19960701
Not Detected	PROMETON	02/25/1999		0.001 mg/L	CXPT 19960701
Not Detected	PRONAMIDE	02/25/1999		0.001 mg/L	CXPT 19960701
Not Detected	PROPACHLOR	02/25/1999		$0.003~\mathrm{mg/L}$	CXPT 19960701
Not Detected	PROPAZINE	02/25/1999		0.001 mg/L	CXPT 19960701
Not Detected	SIMAZINE	02/25/1999	0.004 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	TEBUTHIURON	02/25/1999		0.005 mg/L	CXPT 19960701
Not Detected	TERBACIL	02/25/1999		0.002 mg/L	CXPT 19960701
Not Detected	TOXAPHENE	02/25/1999	$0.003~\mathrm{mg/L}$	0.002 mg/L	CXPT 19960701
Not Detected	TRIFLURALIN	02/25/1999		0.001 mg/L	CXPT 19960701

Laboratory Comments and Result Notes: None

DATE 3/5/99

Drinking Water Laboratory - DWRP Division

3500 N. M.L. King Blvd. Lansing MI 48909

517/335-8184

#### **Official Laboratory Report**

Report To:

City of Rockford Water Plant

7 South Monroe PO Box 561

Rockford MI 49341

Chlorination:

Yes

City of Rockford WSSN / Pool ID: 5730 System Name/Owner:

10 East Bridge, Rockford 49341 Sampled: 02/22/1999 2:00:00PM Collection Address:

**KURT MALZAHN** Received: 02/23/1999 03:22PM Collected By:

Twp/Sec/Well #: ?/?/? Source: Type I

County: Purpose: Routine Monitoring Kent

Collector: Public Water Supply Operator Water System: Treated Public Distribution

Sample Point: WATER PLANT LAB TAP Sample Kit #:

Site Code:

Supplemental Information Related To Reported Result

Sample Number: C1999019192

Customer Number: 73654100

			Health	Minimum	
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code
Not Detected	2.4.5-T	02/26/1999		0.001 mg/L	CXHB 19960701
Not Detected	2.4.5-TP (SILVEX)	02/26/1999	0.05  mg/L	0.0003  mg/L	CXHB 19960701
Not Detected	2.4-D	02/26/1999	0.07 mg/L	0.002 mg/L	CXHB 19960701
Not Detected	ACIFLUORFEN	02/26/1999		0.004 mg/L	CXHB 19960701
Not Detected	BENTAZON	02/26/1999		$0.002~\mathrm{mg/L}$	CXHB 19960701
Not Detected	DICAMBA	02/26/1999		$0.002~\mathrm{mg/L}$	CXHB 19960701
Not Detected	DINOSEB	02/26/1999	0.007 mg/L	0.0003 mg/L	CXHB 19960701
Not Detected	PENTACHLOROPHENOL	02/26/1999	0.001 mg/L	0.00008 mg/L	CXHB 19960701
Not Detected	PICLORAM	02/26/1999	0.5 mg/L	0.002 mg/L	CXHB 19960701

Laboratory Comments and Result Notes: None



Drinking Water Laboratory - DWRP Division

3500 N. M.L. King Blvd, Lansing MI 48909

517/335-8184

## **Official Laboratory Report**



Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C1999019188 Customer Number: 73654100

System Name/Owner:

City of Rockford

WSSN / Pool ID: 5730

Collection Address:

10 East Bridge, Rockford 49341

Sampled: 02/22/1999 2:00:00PM

Collected By:

**KURT MALZAHN** 

Received: 02/23/1999 03:22PM Source: Type I

Twp/Sec/Well #: County: Kent

?/?/?

Purpose: Routine Monitoring

Collector:

Public Water Supply Operator

Water System: Treated Public Distribution

32 Sample Kit #:

Sample Point: WATER PLANT LAB TAP

Page: 1 of 1

Chlorination: Yes

Site Code:

Supplemental Information Related To Reported Result

Test Result	Analyte Name	Tested	Health Limit MCL	Minimum Rpt. Limit	Test Code
23 mg/L	CHLORIDE (AUTOMATED)	02/24/1999		4 mg/L	CRA 19960701
0.8  mg/L	FLUORIDE (AUTOMATED)	02/24/1999	4.0 mg/L	0.1 mg/L	CRA 19960701
160 mg/L	HARDNESS AS CaCO3	02/24/1999		10 mg/L	CRA 19960701
Not Detected	IRON (AUTOMATED)	02/24/1999		0.1 mg/L	CRA 19960701
1.7 mg/L	NITRATE AS N (AUTOMATED)	02/24/1999	10 mg/L	0.4 mg/L	CRA 19960701
Not Detected	NITRITE AS N (AUTOMATED)	02/24/1999	1 mg/L	0.05 mg/L	CRA 19960701
12 mg/L	SODIUM (AUTOMATED)	02/24/1999		5 mg/L	CRA 19960701
92 mg/L	SULFATE (AUTOMATED)	02/24/1999		5 mg/L	CRA 19960701

Laboratory Comments and Result Notes: None

Drinking Water Laboratory - DWRP Division

3500 N. M.I. King Blvd. Lansing MI 48909

517/335-8184

## **Official Laboratory Report**

DAIL 3/1100

Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C1999019191 Customer Number: 73654100

System Name/Owner: City of Rockford

Collection Address: 10 East Bridge. Rockford 49341

Collected By: KURT MALZAHN

Twp/Sec/Well #: ?/?/?

County: Kent

Collector: Public Water Supply Operator

Sample Kit #: 36VO

Chlorination: Yes

WSSN / Pool ID: 5730

Sampled: 02/22/1999 1:50:00PM

Received: 02/23/1999 03:22PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: WATER PLANT LAB TAP

Site Code:

Supplemental Information Related To Reported Result

			Health	Minimum	
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code
Not Detected	BENZENE	02/23/1999	0.005 mg/L	0.0005 mg/L	CXVO 19960701
Not Detected	BROMOBENZENE	02/23/1999		0.0005 mg/L	CXVO 19960701
Not Detected	BROMOCHLOROMETHANE	02/23/1999		0.0005 mg/L	CXVO 19960701
Not Detected	BROMOFORM	02/23/1999	$0.10~\mathrm{mg/L}$	0.0004 mg/L	CXVO 19960701
Not Detected	BROMOMETHANE	02/23/1999		$0.020~\mathrm{mg/L}$	CXVO 19960701
Not Detected	BUTYLBENZENE. NORMAL-	02/23/1999		0.0005 mg/L	CXVO 19960701
Not Detected	BUTYLBENZENE. SEC-	02/23/1999		0.0005 mg/L	CXVO 19960701
Not Detected	BUTYLBENZENE. TERT-	02/23/1999		0.0005 mg/L	CXVO 19960701
Not Detected	CARBON TETRACHLORIDE	02/23/1999	0.005 mg/L	0.0004 mg/L	CXVO 19960701
Not Detected	CHLOROBENZENE	02/23/1999	0.1 mg/L	0.0005 mg/L	CXVO 19960701
Trace	CHLORODIBROMOMETHANE	02/23/1999	0.10 mg/L	0.0004 mg/L	CXVO 19960701
Not Detected	CHLOROETHANE	02/23/1999		$0.020~\mathrm{mg/L}$	CXVO 19960701
0.0061 mg/L	CHLOROFORM	02/23/1999	0.10 mg/L	0.0004 mg/L	CXVO 19960701
Not Detected	CHLOROMETHANE	02/23/1999		$0.05~\mathrm{mg/L}$	CXVO 19960701
Not Detected	CHLOROTOLUENE (COMBINED)	02/23/1999		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	DIBROMO-3-CHLOROPROPANE. 1.2-	02/23/1999		0.0025 mg/L	CXVO 19960701
Not Detected	DIBROMOETHANE 1.2- (EDB)	02/23/1999		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	DIBROMOMETHANE	02/23/1999		0.0005  mg/L	CXVO 19960701
Not Detected	DICHLOROBENZENE.1.2-	02/23/1999	0.6 mg/L	0.0005 mg/L	CXVO 19960701
Not Detected	DICHLOROBENZENE.1.3-	02/23/1999		0.0004 mg/L	CXVO 19960701
Not Detected	DICHLOROBENZENE.1.4-	02/23/1999	0.075  mg/L	0.0004 mg/L	CXVO 19960701
0.0022 mg/L	DICHLOROBROMOMETHANE	02/23/1999	0.10 mg/L	0.0004 mg/L	CXVO 19960701
Not Detected	DICHLOROBUTANE. 1.4-	02/23/1999		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	DICHLORODIFLUOROMETHANE	02/23/1999		0.001 mg/L	CXVO 19960701
Not Detected	DICHLOROETHANE.1.1-	02/23/1999		0.0005 mg/L	CXVO 19960701
Not Detected	DICHLOROETHANE.1.2-	02/23/1999	0.005 mg/L	0.0005 mg/L	CXVO 19960701
Not Detected	DICHLOROETHYLENE.1.1-	02/23/1999	0.007 mg/L	0.0005 mg/L	CXVO 19960701
Not Detected	DICHLOROETHYLENE.1.2-CIS	02/23/1999	0.07 mg/L	0.0004 mg/L	CXVO 19960701
Not Detected	DICHLOROETHYLENE.1.2-TRANS	02/23/1999	0.1 mg/L	0.0004 mg/L	CXVO 19960701
Not Detected	DICHLOROPROPANE.1.2-	02/23/1999	$0.005~\mathrm{mg/L}$	0.0004  mg/L	CXVO 19960701
By authority of I	PA 368 1978 as amended. Process B	atch #: 9022519	l 102 l 02/25	/1999 12:19:16PM	Page: 1 of 2

Official Laboratory Report Sample Number: C1999019191

		Supplemental Information Related To Reported Result					
			Health	Minimum			
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code		
Not Detected	DICHLOROPROPANE.1.3-	02/23/1999		0.001 mg/L	CXVO 19960701		
Not Detected	DICHLOROPROPANE.2.2-	02/23/1999		0.001 mg/L	CXVO 19960701		
Not Detected	DICHLOROPROPENE.1.1-	02/23/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	DICHLOROPROPENE.1.3-CIS	02/23/1999		0.0005  mg/L	CXVO 19960701		
Not Detected	DICHLOROPROPENE.1.3-TRANS	02/23/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	ETHYLBENZENE	02/23/1999	0.7 mg/L	0.0005  mg/L	CXVO 19960701		
Not Detected	FLUOROTRICHLOROMETHANE	02/23/1999		0.001 mg/L	CXVO 19960701		
Not Detected	HEXACHLOROBUTADIENE	02/23/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	HEXACHLOROETHANE	02/23/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	ISOPROPYL BENZENE	02/23/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	ISOPROPYL TOLUENE. PARA-	02/23/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	METHYL ETHYL KETONE	02/23/1999		$0.02~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	METHYL ISOBUTYL KETONE	02/23/1999		$0.02~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	METHYL TERT-BUTYL ETHER	02/23/1999		0.001 mg/L	CXVO 19960701		
Not Detected	METHYLENE CHLORIDE	02/23/1999	0.005 mg/L	0.0006 mg/L	CXVO 19960701		
Not Detected	NAPHTHALENE	02/23/1999		0.001 mg/L	CXVO 19960701		
Not Detected	PROPYLBENZENE. NORMAL-	02/23/1999		$0.0005~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	STYRENE	02/23/1999	0.1 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	TETRACHLOROETHANE.1.1.1.2-	02/23/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	TETRACHLOROETHANE.1.1.2.2-	02/23/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	TETRACHLOROETHYLENE	02/23/1999	0.005 mg/L	0.0004 mg/L	CXVO 19960701		
Not Detected	TETRAHYDROFURAN	02/23/1999		0.005 mg/L	CXVO 19960701		
Not Detected	TOLUENE	02/23/1999	l mg/L	0.0005 mg/L	CXVO 19960701		
0.0083 mg/L	TOTAL TRIHALOMETHANES	02/23/1999	$0.10~\mathrm{mg/L}$	0.0004 mg/L	CXVO 19960701		
Not Detected	TRICHLOROBENZENE.1.2.3-	02/23/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	TRICHLOROBENZENE.1.2.4-	02/23/1999	0.07 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	TRICHLOROETHANE.1.1.1-	02/23/1999	0.2 mg/L	0.0004 mg/L	CXVO 19960701		
Not Detected	TRICHLOROETHANE.1.1.2-	02/23/1999	0.005 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	TRICHLOROETHYLENE	02/23/1999	0.005 mg/L	0.0004 mg/L	CXVO 19960701		
Not Detected	TRICHLOROPROPANE.1.2.3-	02/23/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	TRIMETHYLBENZENE.1.2.4-	02/23/1999		$0.0005~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	TRIMETHYLBENZENE.1.3.5-	02/23/1999		$0.0005~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	VINYL CHLORIDE	02/23/1999	0.002 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	XYLENE. ORTHO-	02/23/1999	10 mg/L	0.0005  mg/L	CXVO 19960701		
Not Detected	XYLENE.META-&PARA-	02/23/1999	10 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	XYLENES (TOTAL)	02/23/1999	10 mg/L	$0.0005~\mathrm{mg/L}$	CXVO 19960701		

Laboratory Comments and Result Notes:

COMPOUNDS REPORTED AS TRACE WERE DETECTED AT LEVELS ABOVE THE DETECTION LIMITS, BUT AT LEVELS TOO LOW TO QUANTITATE.

3/1/99

Drinking Water Laboratory - DWRP Division

3500 N. M.L. King Blvd, Lansing MI 48909

517/335-8184

## **Official Laboratory Report**

Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C1999023922 Customer Number: 73654100

Re-Sample of # C1999019189

City of Rockford System Name/Owner:

Collection Address: 10 East Bridge. Rockford 49341

> **KURT MALZATH** Collected By:

Twp/Sec/Well #: ?/?/?

> County: Kent

Collector: **Public Water Supply Operator** 

Sample Kit #: 36LP

Chlorination: Yes WSSN / Pool ID: 5730

Sampled: 03/29/1999 10:45:00AM

Received: 03/30/1999 01:32PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: PLANT LAB TAP

Site Code:

		Supplemental Information Related To Reported Result					
Test Result	Analyte Name	Tested	Health Limit MCL	Minimun: Rpt. Limit	Test Code		
Not Detected	ALDICARB	04/07/1999		0.001 mg/L	CXLP 19960701		
Not Detected	ALDICARB SULFONE	04/07/1999		0.001 mg/L	CXLP 19960701		
Not Detected	ALDICARB SULFOXIDE	04/07/1999		0.001 mg/L	CXLP 19960701		
Not Detected	CARBARYL	04/07/1999		0.001 mg/L	CXLP 19960701		
Not Detected	CARBOFURAN	: 04/07/1999	0.04 mg/L	0.001 mg/L	CXLP 19960701		
Not Detected	HYDROXYCARBOFURAN. 3-	04/07/1999		0.001 mg/L	CXLP 19960701		
Not Detected	METHIOCARB	04/07/1999		0.001 mg/L	CXLP 19960701		
Not Detected	METHOMYL	04/07/1999		0.001 mg/L	CXLP 19960701		
Not Detected	OXAMYL	04/07/1999	$0.2~\mathrm{mg/L}$	0.001 mg/L	CXLP 19960701		
Not Detected	PROPOXUR (BAYGON)	04/07/1999		0.001 mg/L	CXLP 19960701		

Laboratory Comments and Result Notes:

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

P.O. Box 30270, Lansing, MI 48909

TEL: 517/335-8184 FAX: 517/335-8562

## Official Laboratory Report



Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C1999036631 Customer Number: 73654100

System Name/Owner:

City of Rockford

Collection Address:

10 East Bridge, Rockford 49341

Collected By:

**KURT MALZAHN** 

Twp/Sec/Well #:

?/?/?

County:

Kent

Collector:

Public Water Supply Operator

Sample Kit #:

**36VO** 

36EN?

Chlorination:

Yes

WSSN / Pool ID: 5730

Sampled: 06/22/1999 1:05:00PM

Received: 06/23/1999 01:29PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: WATER PLANT LAB TAP

Site Code:

Supplemental Information Related To Reported Result

Test Result Analyte Name

Tested

Health Limit MCL Minimum Rpt. Limit

**Test Code** 

Page: 1 of 1

Not Detected ENDOTHALL

06/28/1999

0.1 mg/L

0.01 mg/L

CXEN 19960701

Laboratory Comments and Result Notes:

THE RECOMMENDED EPA SAMPLE HOLDING TIME FOR THIS ANALYSIS WAS

**EXCEEDED** 

**DWRP Laboratory Services - Drinking Water Lab** USEPA Region V Drinking Water Lab Cert. No. MI00003

P.O. Box 30270, Lansing, MI 48909

TEL: 517/335-8184 FAX: 517/335-8562

#### Official Laboratory Report

7/15/99 DAIL 7/15/99

Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C1999036626 Customer Number: 73654100

System Name/Owner:

City of Rockford

Collection Address:

140 East Bridge, Rockford 49341

Collected By:

**KURT MALZATH** 

Twp/Sec/Well #:

?/?/?

County:

Kent

Collector: Sample Kit #: Other

Chlorination:

**36VO** 

Yes

WSSN / Pool ID: 5730

Sampled: 06/22/1999 1:30:00PM

Received: 06/23/1999 01:29PM Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: SINK TAP

Site Code: L-2

Supplemental Information Related To Reported Result

Test Result Analyte Name

**Tested** 

**Minimum** Health Limit MCL

Test Code

NO TEST

NO TESTING - MESSAGE ONLY

07/12/1999

Rpt. Limit

CNONE 19960715

Page: 1 of 1

Laboratory Comments and Result Notes:

SAMPLE ANALYSIS NOT COMPLETED. SAMPLE LOST IN LABORATORY ACCIDENT.

Process Batch #: 9071347 1 282 | 07/13/1999 07:17:32AM

By authority of PA 368 1978 as amended.

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

P.O. Box 30270, Lansing, MI 48909

TEL: 517/335-8184 FAX: 517/335-8562

#### Official Laboratory Report



Report To:

City of Rockford Water Plant

7 South Monroe PO Box 561 Rockford MI 49341 Sample Number: C1999036632 Customer Number: 73654100

System Name/Owner: Collection Address:

City of Rockford

10 East Bridge, Rockford 49341

Collected By:

KURT MALZAHN

Twp/Sec/Well #:

?/?/?

County:

Kent

Collector:

Public Water Supply Operator

Sample Kit #:

36DQ

Chlorination: Yes

WSSN / Pool ID: 5730

Sampled: 06/22/1999 1:00:00PM Received: 06/23/1999 01:29PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: WATER PLANT LAB TAP

Site Code:

			Supplemental Information Related To Reported Result				
Test Result	Analyte Name		Tested	Health Limit MCL	Minimum Rpt. Limit	Test Code	
Not Detected	DIQUAT	1	06/30/1999	0.02 mg/L	0.005 mg/L	CXDQ 19960701	

Laboratory Comments and Result Notes:

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

P.O. Box 30270, Lansing, MI 48909

TEL: 517/335-8184 FAX: 517/335-8562

#### Official Laboratory Report



Report To:

City of Rockford Water Plant

7 South Monroe PO Box 561

Rockford MI 49341

Sample Number: C1999036627 Customer Number: 73654100

System Name/Owner: City of Rockford

Collection Address: 10 East Bridge, Rockford 49341

Collected By: KURT MALZATH

Twp/Sec/Well #: ?/?/?

County: Kent

Collector: Public Water Supply Operator

Sample Kit #: 36LP

Chlorination: Yes

WSSN / Pool ID: 5730

Sampled: 06/22/1999 1:00:00PM

Received: 06/23/1999 01:29PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: WATER PLANT LAB TAP

Site Code:

Supplemental Information Related To Reported Result

			Health	Minimum	
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code
Not Detected	ALDICARB	06/24/1999		0.001 mg/L	CXLP 19960701
Not Detected	ALDICARB SULFONE	06/24/1999		0.001 mg/L	CXLP 19960701
Not Detected	ALDICARB SULFOXIDE	06/24/1999		0.001 mg/L	CXLP 19960701
Not Detected	CARBARYL	06/24/1999		0.001 mg/L	CXLP 19960701
Not Detected	CARBOFURAN	06/24/1999	0.04 mg/L	0.001 mg/L	CXLP 19960701
Not Detected	HYDROXYCARBOFURAN, 3-	06/24/1999		0.001 mg/L	CXLP 19960701
Not Detected	METHIOCARB	06/24/1999		0.001 mg/L	CXLP 19960701
Not Detected	METHOMYL	06/24/1999		0.001 mg/L	CXLP 19960701
Not Detected	OXAMYL	06/24/1999	0.2 mg/L	0.001 mg/L	CXLP 19960701
Not Detected	PROPOXUR (BAYGON)	06/24/1999		0.001 mg/L	CXLP 19960701

Laboratory Comments and Result Notes:

None

Process Batch #: 9062876 | 288 | 06/28/1999 09:00:27AM

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

P.O. Box 30270, Lansing, MI 48909

TEL: 517/335-8184 FAX: 517/335-8562

#### Official Laboratory Report



Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C1999036629 Customer Number: 73654100

System Name/Owner:

City of Rockford

Collection Address:

10 East Bridge, Rockford 49341

Collected By:

**KURT MALZAHN** 

Twp/Sec/Well #:

?/?/?

County: Collector:

Public Water Supply Operator

Sample Kit #:

36HB

Chlorination: Yes

WSSN / Pool ID: 5730

Sampled: 06/22/1999 1:10:00PM Received: 06/23/1999 01:29PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution
Sample Point: WATER PLANT LAB TAP

Site Code:

		;	Supplemental Information Related To Reported Result				
Took Damile	Analyta Nama	'	Tested	Health Limit MCL	Minimum Rpt. Limit	Test Code	
Test Result	Analyte Name	<del></del>		Linut MCL			
Not Detected	2,4,5-T	 	06/25/1999		0.001 mg/L	CXHB 19960701	
Not Detected	2,4,5-TP (SILVEX)	 	06/25/1999	0.05 mg/L	0.0003 mg/L	CXHB 19960701	
Not Detected	2,4-D	I .	06/25/1999	0.07 mg/L	0.002 mg/L	CXHB 19960701	
Not Detected	ACIFLUORFEN	! !	06/25/1999		0.004 mg/L	CXHB 19960701	
Not Detected	BENTAZON	1	06/25/1999		0.002  mg/L	CXHB 19960701	
Not Detected	DICAMBA	! !	06/25/1999		0.002 mg/L	CXHB 19960701	
Not Detected	DINOSEB	! !	06/25/1999	0.007 mg/L	0.0003 mg/L	CXHB 19960701	
Not Detected	PENTACHLOROPHENOL	1	06/25/1999	0.001 mg/L	0.00008 mg/L	CXHB 19960701	
Not Detected	PICLORAM	! 	06/25/1999	0.5 mg/L	0.002 mg/L	CXHB 19960701	

Laboratory Comments and Result Notes:

None

Process Batch #: 9062971 | 163 | 06/29/1999 03:15:36PM

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003 P.O. Box 30270, Lansing, MI 48909-7770

TEL: 517/335-8184 FAX: 517/335-8562

## Official Laboratory Report

Report To:

City of Rockford Water Plant 7 South Monroe PO Box 561 Rockford MI 49341 Sample Number: C1999036630

Customer Number: 73654100

System Name/Owner: CITY OF ROCKFORD

Collection Address: 10 East Bridge, Rockford 49341

Collected By: KURT MALZAHN

Twp/Sec/Well #: ?/?/?

County: Kent

Sample Point: WATER PLANT LAB TAP

Sample Kit #: 36HA

Chlorination: Yes

WSSN / Pool ID: 5730

Source: Type I

Site Code:

Collector: Other

Sample Date: 06/22/1999 1:05:00PM

Received: 06/23/1999 1:29:00PM

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Test Result	Analyte Name	Tested	Limit MCL	Rpt Limit	Tes	st Performed
Not Detected	BROMOACETIC ACID	07/07/1999		0.004 mg/L	CXHA	19960701
.005 mg/L	BROMOCHLOROACETIC ACID	07/07/1999		0.001 mg/L	CXHA	19960701
Trace	CHLOROACETIC ACID	07/07/1999		0.004 mg/L	CXHA	19960701
Not Detected	DALAPON	07/07/1999	0.2 mg/L	0.001 mg/L	CXHA	19960701
Trace	DIBROMOACETIC ACID	07/07/1999		0.001 mg/L	CXHA	19960701
.027 mg/L	DICHLOROACETIC ACID	07/07/1999		0.002 mg/L	CXHA	19960701
<.011 mg/L	TRICHLOROACETIC ACID	07/07/1999		0.001 mg/L	CXHA	19960701

#### Lab Comments:

COMPOUNDS REPORTED AS TRACE WERE DETECTED AT LEVELS ABOVE THE DETECTION LIMITS, BUT AT LEVELS TOO LOW TO QUANTITATE.

CORRECTED REPORT: QC INDICATES THAT THE TRUE VALUE FOR TRICHLOROACETIC ACID IS LESS THAN THE VALUE REPORTED.



**DWRP Laboratory Services - Drinking Water Lab** sing USEPA Region V Drinking Water Lab Cert. No. MI00003 P.O. Box 30270, Lansing, MI 48909-7770

TEL: 517/335-8184 FAX: 517/335-8562

## Official Laboratory Report

Report To:

City of Rockford Water Plant

7 South Monroe PO Box 561 Rockford MI 49341 Laboratory: Lansing

Sample Number: C1999036630

01/28/2000

System Name/Owner: CITY OF ROCKFORD

Collection Address: 10 East Bridge, Rockford 49341

Collected By: KURT MALZAHN

Twp/Sec/Well #: ?/?/?

County: Kent

Collector: KURT MALZAHN

Sample Kit #: 36HA

Chlorination: Yes

Date Collected: 06/22/1999

Received: 06/23/1999

WSSN / Pool ID: 5730

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution Sample Point: WATER PLANT LAB TAP

Site Code:

Test Result	Analyte Name	Tested	Limit MCL	Rpt Limit	Tes	st Performed
Not Detected	BROMOACETIC ACID	07/07/1999		0.004 mg/L	CXHA	19960701
.005	BROMOCHLOROACETIC ACID	07/07/1999		0.001 mg/L	CXHA	19960701
Trace	CHLOROACETIC ACID	07/07/1999		0.004 mg/L	CXHA	19960701
Not Detected	DALAPON	07/07/1999	0.2 mg/L	0.001 mg/L	CXHA	19960701
Trace	DIBROMOACETIC ACID	07/07/1999		0.001 mg/L	CXHA	19960701
.027	DICHLOROACETIC ACID	07/07/1999		0.002 mg/L	CXHA	19960701
<.011	TRICHLOROACETIC ACID	07/07/1999		0.001 mg/L	CXHA	19960701

#### Lab Comments:

COMPOUNDS REPORTED AS TRACE WERE DETECTED AT LEVELS ABOVE THE DETECTION LIMITS, BUT AT LEVELS TOO LOW TO QUANTITATE.

CORRECTED REPORT: QC INDICATES THAT THE TRUE VALUE FOR TRICHLOROACETIC ACID IS LESS THAN THE VALUE REPORTED.

: 39


Page: 1 of 1

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

P.O. Box 30270, Lansing, MI 48909

TEL: 517/335-8184 FAX: 517/335-8562

## Official Laboratory Report



Report To:

City of Rockford Water Plant

7 South Monroe PO Box 561

Rockford MI 49341

Sample Number: C1999036628 Customer Number: 73654100

System Name/Owner:

wner: City of Rockford

Collection Address: 10 East Bridge, Rockford 49341

Collected By:

**KURT MALZAHN** 

Twp/Sec/Well #:

?/?/? Kent

County: Collector:

Public Water Supply Operator

Sample Kit #:

36NV

Chlorination:

Yes

WSSN / Pool ID: 5730

Sampled: 06/22/1999 1:10:00PM Received: 06/23/1999 01:29PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: WATER PLANT LAB TAP

Site Code:


Supplemental Information Related To Reported Result

		3	appiemental inform	ation Related to Repor	ted Result
			Health	Minimum	
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code
Not Detected	ALACHLOR	06/24/1999	0.002 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	ALDRIN	06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	AMETRYN	06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	ATRAZINE	06/24/1999	0.003  mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	BROMACIL	06/24/1999		0.002 mg/L	CXPT 19960701
Not Detected	BUTACHLOR	06/24/1999		$0.002~\mathrm{mg/L}$	CXPT 19960701
Not Detected	BUTYLATE	06/24/1999		0.002 mg/L	CXPT 19960701
Not Detected	CARBOXIN	06/24/1999		0.002 mg/L	CXPT 19960701
Not Detected	CHLORDANE, alpha	06/24/1999	0.002 mg/L	0.0002  mg/L	CXPT 19960701
Not Detected	CHLORDANE,gamma-	06/24/1999	0.002 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	CHLOROTHALONIL	06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	CYANAZINE	06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	CYCLOATE	06/24/1999		0.002 mg/L	CXPT 19960701
Not Detected	CYPRAZINE	06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	DACTHAL	06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	DDD,4,4'-	06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	DDE,4,4'-	06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	DDT,4,4'-	06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	DIELDRIN	: 06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	DIPHENAMID	06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	ENDOSULFAN, alpha	66/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	ENDOSULFAN,beta	06/24/1999		0.001 mg/L	CXPT 19960701
Not Detected	ENDRIN	06/24/1999	0.002 mg/L	0.00005 mg/L	CXPT 19960701
Not Detected	ENDRIN ALDEHYDE	06/24/1999	_	0.001 mg/L	CXPT 19960701
By authority of I	PA 368 1978 as amended.	Process Batch #: 9070240	1 559 1 07/0	2/1999 03:51:33PM	Page: 1 of 2

		Supplemental Information Related To Reported Result				
			Health	Minimum		
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code	
Not Detected	EPTAM	06/24/1999		0.001 mg/L	CXPT 19960701	
Not Detected	HEPTACHLOR	06/24/1999	0.0004 mg/L	0.00008 mg/L	CXPT 19960701	
Not Detected	HEPTACHLOR EPOXIDE	06/24/1999	0.0002 mg/L	0.00004 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROBENZENE	06/24/1999	0.001 mg/L	0.0001 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROCYCLOHEXANE	06/24/1999		0.001 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROCYCLOHEXANE (BETA-BHC)	06/24/1999		0.001 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROCYCLOHEXANE	06/24/1999		0.001 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROCYCLOPENTADIENE	06/24/1999	0.05 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	HEXAZINONE	06/24/1999		0.003 mg/L	CXPT 19960701	
Not Detected	LINDANE (GAMMA-BHC)	06/24/1999	0.0002 mg/L	$0.00004~\mathrm{mg/L}$	CXPT 19960701	
Not Detected	METHOXYCHLOR	06/24/1999	0.04 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	METOLACHLOR	06/24/1999		0.001 mg/L	CXPT 19960701	
Not Detected	METRIBUZIN	06/24/1999		0.001 mg/L	CXPT 19960701	
Not Detected	OCTACHLOROCYCLOPENTENE	06/24/1999		0.001 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1016)	06/24/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1221)	06/24/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1232)	06/24/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1242)	06/24/1999	0.0005 mg/L	$0.0002~\mathrm{mg/L}$	CXPT 19960701	
Not Detected	PCB (AROCLOR 1248)	06/24/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1254)	06/24/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1260)	06/24/1999	0.0005  mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	POLYBROMINATED BIPHENYLS	06/24/1999		0.001 mg/L	CXPT 19960701	
Not Detected	PROMETON	06/24/1999		0.001 mg/L	CXPT 19960701	
Not Detected	PRONAMIDE	06/24/1999		0.001 mg/L	CXPT 19960701	
Not Detected	PROPACHLOR	06/24/1999		0.003 mg/L	CXPT 19960701	
Not Detected	PROPAZINE	06/24/1999		0.001 mg/L	CXPT 19960701	
Not Detected	SIMAZINE	06/24/1999	0.004 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	TEBUTHIURON	06/24/1999		0.005 mg/L	CXPT 19960701	
Not Detected	TERBACIL	06/24/1999		0.002 mg/L	CXPT 19960701	
Not Detected	TOXAPHENE	06/24/1999	0.003 mg/L	$0.002~\mathrm{mg/L}$	CXPT 19960701	
Not Detected	TRIFLURALIN	06/24/1999		0.001 mg/L	CXPT 19960701	

Laboratory Comments and Result Notes:





P.O. Box 30270, Lansing, MI 48909

TEL: 517/335-8184 FAX: 517/335-8562

RECEIVED JUL 1 9 1999

Official Laboratory Report

Report To:

City of Rockford Water Plant

7 South Monroe PO Box 561

Rockford MI 49341

Sample Number: C1999036630 Customer Number: 73654100

System Name/Owner: CITY OF ROCKFORD WSSN / Pool ID: 5730

Collection Address: 10 East Bridge, Rockford 49341 Sampled: 06/22/1999 1:05:00PM

Collected By: KURT MALZAHN Received: 06/23/1999 01:29PM

Twp/Sec/Well #: ?/?/? Source: Type I

County: Kent Purpose: Routine Monitoring

Collector: Other Water System: Treated Public Distribution
Sample Kit #: 36HA Sample Point: WATER PLANT LAB TAP

Chlorination: Yes Site Code:

	l	Supplemental Information Related To Reported Result					
Test Result	Analyte Name	Tested	Health Limit MCL	Minimum Rpt. Limit	Test Code		
Not Detected	BROMOACETIC ACID	07/07/1999		0.004 mg/L	CXHA 19960701		
.005 mg/L	BROMOCHLOROACETIC ACID	07/07/1999		0.001 mg/L	CXHA 19960701		
Trace	CHLOROACETIC ACID	07/07/1999		0.004 mg/L	CXHA 19960701		
Not Detected	DALAPON	07/07/1999	0.2 mg/L	0.001 mg/L	CXHA 19960701		
Тгасе	DIBROMOACETIC ACID	07/07/1999		0.001 mg/L	CXHA 19960701		
.027 mg/L	DICHLOROACETIC ACID	07/07/1999		0.002 mg/L	CXHA 19960701		
.011 mg/L	TRICHLOROACETIC ACID	07/07/1999		0.001 mg/L	CXHA 19960701		

Laboratory Comments and Result Notes:

COMPOUNDS REPORTED AS TRACE WERE DETECTED AT LEVELS ABOVE THE DETECTION LIMITS, BUT AT LEVELS TOO LOW TO QUANTITATE.

Process Batch #: 9071565 | 511 | 07/15/1999 07:01:30AM

Page: 1 of 1

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

> P.O. Box 30270, Lansing, MI 48909 TEL: 517/335-8184 FAX: 517/335-8562

### Official Laboratory Report

DATE 9/1/199

#### Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C1999041454 Customer Number: 73654100

System Name/Owner:

City of Rockford

Collection Address:

140 East Bridge, Rockford 49341

Collected By:

**KURT MALZAHN** 

Twp/Sec/Well #:

?/?/?

County:

Kent

Collector:

Public Water Supply Operator

Sample Kit #:

36VO

Chlorination: Yes

WSSN / Pool ID: 5730

Sampled: 07/19/1999 12:15:00PM Received: 07/20/1999 03:18PM

Source: Type I

Purpose: Other

Water System: Treated Public Distribution

Sample Point: SINK TAP

Site Code: L-2

		Supplemental Information Related To Reported Result				
			Health	Minimum		
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code	
Not Detected	BENZENE	07/23/1999	0.005 mg/L	0.0005 mg/L	CXVO 19960701	
Not Detected	BROMOBENZENE	07/23/1999		0.0005 mg/L	CXVO 19960701	
Not Detected	BROMOCHLOROMETHANE	07/23/1999		0.0005 mg/L	CXVO 19960701	
Not Detected	BROMOFORM	07/23/1999	0.10 mg/L	0.0004 mg/L	CXTM 19960701	
Not Detected	BROMOFORM	07/23/1999	0.10 mg/L	0.0004 mg/L	CXVO 19960701	
Not Detected	BROMOMETHANE	07/23/1999		$0.020~\mathrm{mg/L}$	CXVO 19960701	
Not Detected	BUTYLBENZENE, NORMAL-	07/23/1999		0.0005 mg/L	CXVO 19960701	
Not Detected	BUTYLBENZENE, SEC-	07/23/1999		0.0005 mg/L	CXVO 19960701	
Not Detected	BUTYLBENZENE, TERT-	07/23/1999		0.0005 mg/L	CXVO 19960701	
Not Detected	CARBON TETRACHLORIDE	07/23/1999	0.005 mg/L	0.0004 mg/L	CXVO 19960701	
Not Detected	CHLOROBENZENE	07/23/1999	0.1 mg/L	0.0005 mg/L	CXVO 19960701	
0.0045 mg/L	CHLORODIBROMOMETHANE	07/23/1999	0.10 mg/L	0.0004 mg/L	CXVO 19960701	
0.0045 mg/L	CHLORODIBROMOMETHANE	07/23/1999	0.10 mg/L	0.0004 mg/L	CXTM 19960701	
Not Detected	CHLOROETHANE	07/23/1999		0.020  mg/L	CXVO 19960701	
0.0453 mg/L	CHLOROFORM	07/23/1999	0.10 mg/L	0.0004 mg/L	CXTM 19960701	
0.0453 mg/L	CHLOROFORM	07/23/1999	0.10 mg/L	0.0004 mg/L	CXVO 19960701	
Not Detected	CHLOROMETHANE	07/23/1999		0.05 mg/L	CXVO 19960701	
Not Detected	CHLOROTOLUENE (COMBINED)	07/23/1999		0.0005 mg/L	CXVO 19960701	
Not Detected	DIBROMO-3-CHLOROPROPANE, 1,2-	07/23/1999		0.0025 mg/L	CXVO 19960701	
Not Detected	DIBROMOETHANE 1,2- (EDB)	07/23/1999		0.0005 mg/L	CXVO 19960701	
Not Detected	DIBROMOMETHANE	07/23/1999		0.0005 mg/L	CXVO 19960701	
Not Detected	DICHLOROBENZENE,1,2-	07/23/1999	0.6 mg/L	0.0005 mg/L	CXVO 19960701	
Not Detected	DICHLOROBENZENE,1,3-	07/23/1999	-	0.0004 mg/L	CXVO 19960701	
Not Detected	DICHLOROBENZENE,1,4-	07/23/1999	0.075 mg/L	0.0004 mg/L	CXVO 19960701	
By authority of I	PA 368 1978 as amended. Process I	Batch #: 9090271	I 178 I 09/02	/1999 11:29:12AN	1 Page: 1 of 3	

DWRP Laboratory Services - Drinking Water Lab PP181013140

USEPA Region V Drinking Water Lab Cert. No. MI00003

P.O. Box 30270, Lansing, MI 48909 TEL: 517/335-8184 FAX: 517/335-8562

Official Laboratory Report



City Of Rockford 10 East Bridge PO Box 561

Rockford MI 49341

Sample Number: C1999047313 Customer Number: 76453000

Re-Sample of # C1999036631

System Name/Owner:

City Of Rockford

Collection Address:

Water Plant Lab 10 East Bridge, Rockford 4934

Collected By:

**DENNIS BRINKS** 

Twp/Sec/Well #:

?/?/?

County:

Kent

Collector:

Public Water Supply Operator

Sample Kit #:

36EN

Chlorination:

Yes

WSSN / Pool ID: 5730

Sampled: 08/19/1999 3:52:00PM Received: 08/20/1999 10:50AM

Source: Surface Water

Purpose: Other

Water System: Treated Public Distribution

Sample Point: LAB TAP

Site Code:

	Su	applemental Inform	ation Related To Repo	rted Result
Test Result Analyte Name	Tested	Health Limit MCL	Minimum Rpt. Limit	Test Code
Not Detected ENDOTHALL	08/24/1999	0.1 mg/L	0.01 mg/L	CXEN 19960701


Laboratory Comments and Result Notes:

THE RECOMMENDED EPA SAMPLE HOLDING TIME FOR THIS ANALYSIS WAS EXCEEDEDTHE RECOMMENDED EPA SAMPLE HOLDING TIME FOR THIS ANALYSIS WAS EXCEEDED

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

> P.O. Box 30270, Lansing, MI 48909 TEL: 517/335-8184 FAX: 517/335-8562

#### Official Laboratory Report



#### Report To:

City of Rockford Water Plant

7 South Monroe PO Box 561

Rockford MI 49341

Sample Number: C1999049721 Customer Number: 73654100

System Name/Owner: Collection Address:

By authority of PA 368 1978 as amended.

City of Rockford

10 East Bridge, Rockford 49341

Collected By: **KURT MALZAHN** 

Twp/Sec/Well #: ?/?/?

Kent

County: Collector:

Public Water Supply Operator Sample Kit #:

Chlorination: Yes

WSSN / Pool ID: 5730

Sampled: 09/01/1999 4:24:00PM Received: 09/02/1999 01:53PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: PLANT LAB TAP

Site Code:

50 | 09/21/1999 11:50:17AM

Page: 1 of 2

		Si	Supplemental Information Related To Reported Result					
Test Result	Analyte Name	   Tested	Health Limit <u>MCL</u>	Minimum Rpt. Limit	Test Code			
Not Detected	ALACHLOR	09/03/1999	0.002 mg/L	0.0002 mg/L	CXPT 19960701			
Not Detected	ALDRIN	09/03/1999	0.002 mg/L	0.0002 mg/L 0.001 mg/L	CXPT 19960701			
Not Detected	AMETRYN	09/03/1999		0.001 mg/L	CXPT 19960701			
Not Detected	ATRAZINE	09/03/1999	0.003 mg/L	0.0002 mg/L	CXPT 19960701			
Not Detected	BROMACIL	09/03/1999	0.003 mg/L	0.002 mg/L	CXPT 19960701			
Not Detected	BUTACHLOR	09/03/1999		0.002 mg/L	CXPT 19960701			
Not Detected	BUTYLATE	09/03/1999		0.002 mg/L	CXPT 19960701			
Not Detected	CARBOXIN	09/03/1999		0.002 mg/L	CXPT 19960701			
Not Detected	CHLORDANE, alpha	09/03/1999	0.002 mg/L	0.0002 mg/L	CXPT 19960701			
Not Detected	CHLORDANE,gamma-	09/03/1999	0.002 mg/L	0.0002 mg/L	CXPT 19960701			
Not Detected	CHLOROTHALONIL	09/03/1999	_	0.001 mg/L	CXPT 19960701			
Not Detected	CYANAZINE	09/03/1999		0.001 mg/L	CXPT 19960701			
Not Detected	CYCLOATE	09/03/1999		0.002 mg/L	CXPT 19960701			
Not Detected	CYPRAZINE	09/03/1999		0.001 mg/L	CXPT 19960701			
Not Detected	DACTHAL	09/03/1999		0.001 mg/L	CXPT 19960701			
Not Detected	DDD,4,4'-	09/03/1999		0.001 mg/L	CXPT 19960701			
Not Detected	DDE,4,4'-	09/03/1999		0.001 mg/L	CXPT 19960701			
Not Detected	DDT,4,4'-	09/03/1999		0.001 mg/L	CXPT 19960701			
Not Detected	DIELDRIN	09/03/1999		0.001 mg/L	CXPT 19960701			
Not Detected	DIPHENAMID	09/03/1999		0.001 mg/L	CXPT 19960701			
Not Detected	ENDOSULFAN, alpha	09/03/1999		0.001 mg/L	CXPT 19960701			
Not Detected	ENDOSULFAN,beta	09/03/1999		0.001 mg/L	CXPT 19960701			
Not Detected	ENDRIN	09/03/1999	0.002 mg/L	0.00005 mg/L	CXPT 19960701			
Not Detected	ENDRIN ALDEHYDE	09/03/1999		0.001 mg/L	CXPT 19960701			

Process Batch #: 9092161

	ation Related To Repo	rted Result			
		1	Health	Minimum	
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code
Not Detected	EPTAM	09/03/1999		0.001 mg/L	CXPT 19960701
Not Detected	HEPTACHLOR	09/03/1999	0.0004 mg/L	0.00008 mg/L	CXPT 19960701
Not Detected	HEPTACHLOR EPOXIDE	09/03/1999	0.0002 mg/L	0.00004 mg/L	CXPT 19960701
Not Detected	HEXACHLOROBENZENE	09/03/1999	0.001 mg/L	0.0001 mg/L	CXPT 19960701
Not Detected	HEXACHLOROCYCLOHEXANE	09/03/1999		0.001 mg/L	CXPT 19960701
Not Detected	HEXACHLOROCYCLOHEXANE (BETA-BHC)	09/03/1999		0.001 mg/L	CXPT 19960701
Not Detected	HEXACHLOROCYCLOHEXANE	09/03/1999		0.001 mg/L	CXPT 19960701
Not Detected	HEXACHLOROCYCLOPENTADIENE	09/03/1999	0.05 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	HEXAZINONE	09/03/1999		0.003 mg/L	CXPT 19960701
Not Detected	LINDANE (GAMMA-BHC)	09/03/1999	0.0002 mg/L	0.00004 mg/L	CXPT 19960701
Not Detected	METHOXYCHLOR	09/03/1999	0.04 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	METOLACHLOR	09/03/1999		0.001 mg/L	CXPT 19960701
Not Detected	METRIBUZIN	09/03/1999		0.001 mg/L	CXPT 19960701
Not Detected	OCTACHLOROCYCLOPENTENE	09/03/1999		0.001 mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1016)	09/03/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1221)	09/03/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1232)	09/03/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1242)	09/03/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1248)	09/03/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	PCB (AROCLOR 1254)	09/03/1999	0.0005 mg/L	$0.0002~\mathrm{mg/L}$	CXPT 19960701
Not Detected	PCB (AROCLOR 1260)	09/03/1999	0.0005 mg/L	$0.0002~\mathrm{mg/L}$	CXPT 19960701
Not Detected	POLYBROMINATED BIPHENYLS	09/03/1999		0.001 mg/L	CXPT 19960701
Not Detected	PROMETON	09/03/1999		0.001 mg/L	CXPT 19960701
Not Detected	PRONAMIDE	09/03/1999		0.001 mg/L	CXPT 19960701
Not Detected	PROPACHLOR	09/03/1999		0.003 mg/L	CXPT 19960701
Not Detected	PROPAZINE	09/03/1999		0.001 mg/L	CXPT 19960701
Not Detected	SIMAZINE	09/03/1999	0.004 mg/L	0.0002 mg/L	CXPT 19960701
Not Detected	TEBUTHIURON	09/03/1999		$0.005~\mathrm{mg/L}$	CXPT 19960701
Not Detected	TERBACIL	09/03/1999		0.002  mg/L	CXPT 19960701
Not Detected	TOXAPHENE	09/03/1999	0.003 mg/L	0.002  mg/L	CXPT 19960701
Not Detected	TRIFLURALIN	09/03/1999		0.001 mg/L	CXPT 19960701

Laboratory Comments and Result Notes:

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

P.O. Box 30270, Lansing, MI 48909

TEL: 517/335-8184 FAX: 517/335-8562

Official Laboratory Report

Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C1999049720 Customer Number: 73654100

System Name/Owner:

City of Rockford

Collection Address:

10 East Bridge, Rockford 49341

Collected By:

**KURT MALZALH** 

Twp/Sec/Well #:

?/?/?

County:

Kent

Collector: Public Water Supply Operator

Sample Kit #:

36NV

Chlorination: Yes

WSSN / Pool ID: 5730

Sampled: 09/01/1999 4:26:00PM

Received: 09/02/1999 01:53PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: PLANT LAB TAP

Site Code:

Supplemental Information Related To Reported Result

Test Result	Analyte Name	Teste	ed	Health Limit MCL	Minimum Rpt. Limit	Test Code
Not Detected	2,4,5-T	09/08	3/1999		0.001 mg/L	CXHB 19960701
Not Detected	2,4,5-TP (SILVEX)	09/08	/1999	0.05 mg/L	0.0003 mg/L	CXHB 19960701
Not Detected	2,4-D	09/08	/1999	0.07 mg/L	0.002 mg/L	CXHB 19960701
Not Detected	ACIFLUORFEN	09/08	/1999		0.004  mg/L	CXHB 19960701
Not Detected	BENTAZON	L 09/08	/1999		0.002 mg/L	CXHB 19960701
Not Detected	DICAMBA	09/08	/1999		0.002 mg/L	CXHB 19960701
Not Detected	DINOSEB	09/08	/1999	0.007 mg/L	0.0003 mg/L	CXHB 19960701
Not Detected	PENTACHLOROPHENOL	09/08	/1999	0.001 mg/L	0.00008 mg/L	CXHB 19960701
Not Detected	PICLORAM	09/08	/1999	0.5 mg/L	0.002 mg/L	CXHB 19960701

Laboratory Comments and Result Notes:

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

> P.O. Box 30270, Lansing, MI 48909 TEL: 517/335-8184 FAX: 517/335-8562

> Official Laboratory Report



#### Report To:

City of Rockford Water Plant

7 South Monroe PO Box 561

Rockford MI 49341

Sample Number: C1999049719 Customer Number: 73654100

System Name/Owner: Collection Address:

City of Rockford

10 East Bridge, Rockford 49341

Collected By:

**KURT MALZALH** 

Twp/Sec/Well #:

?/?/?

County:

Kent

Collector:

Public Water Supply Operator

Sample Kit #:

36LPA

Chlorination: Yes

WSSN / Pool ID: 5730

Sampled: 09/01/1999 4:20:00PM

Received: 09/02/1999 01:53PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: PLANT LAB TAP

Site Code:

	<del></del> -		Supplemental Information Related To Reported Result				
			Health	Minimum			
Test Result	Analyte Name	Tested	<u>Limit MCL</u>	Rpt. Limit	Test Code		
Not Detected	ALDICARB	09/28/1999	)	0.001 mg/L	CXLP 19960701		
Not Detected	ALDICARB SULFONE	09/28/1999	)	0.001 mg/L	CXLP 19960701		
Not Detected	ALDICARB SULFOXIDE	09/28/1999	)	0.001 mg/L	CXLP 19960701		
Not Detected	CARBARYL	09/28/1999	)	0.001 mg/L	CXLP 19960701		
Not Detected	CARBOFURAN	09/28/1999	0.04 mg/L	0.001 mg/L	CXLP 19960701		
Not Detected	HYDROXYCARBOFURAN, 3-	09/28/1999	)	0.001 mg/L	CXLP 19960701		
Not Detected	METHIOCARB	09/28/1999	•	0.001 mg/L	CXLP 19960701		
Not Detected	METHOMYL	09/28/1999	1	0.001 mg/L	CXLP 19960701		
Not Detected	OXAMYL	09/28/1999	0.2 mg/L	0.001 mg/L	CXLP 19960701		
Not Detected	PROPOXUR (BAYGON)	09/28/1999	)	0.001 mg/L	CXLP 19960701		

Laboratory Comments and Result Notes:

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

> P.O. Box 30270, Lansing, MI 48909 TEL: 517/335-8184 FAX: 517/335-8562

## Official Laboratory Report

Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C2000003092 Customer Number: 73654100

O,

System Name/Owner:

City of Rockford

Collection Address:

10 East Bridge, Rockford 49341

Collected By:

**DENNIS BRINKS** 

Twp/Sec/Well #:

?/?/?

County:

Kent

Collector:

Public Water Supply Operator

Sample Kit #: Chlorination:

Yes

36LPA

WSSN / Pool ID: 5730

Sampled: 10/26/1999 2:26:00PM

Received: 10/27/1999 01:13PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: PLANT LAB TAP

Site Code:

		Supplemental Information Related To Reported Result				
		i	Health	Minimum		
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code	
Not Detected	ALDICARB	11/08/1999		0.001 mg/L	CXLP 19960701	
Not Detected	ALDICARB SULFONE	11/08/1999		0.001 mg/L	CXLP 19960701	
Not Detected	ALDICARB SULFOXIDE	11/08/1999		0.001 mg/L	CXLP 19960701	
Not Detected	CARBARYL	11/08/1999		0.001 mg/L	CXLP 19960701	
Not Detected	CARBOFURAN	11/08/1999	0.04 mg/L	0.001 mg/L	CXLP 19960701	
Not Detected	HYDROXYCARBOFURAN, 3-	11/08/1999		0.001 mg/L	CXLP 19960701	
Not Detected	METHIOCARB	11/08/1999		0.001 mg/L	CXLP 19960701	
Not Detected	METHOMYL	11/08/1999		0.001 mg/L	CXLP 19960701	
Not Detected	OXAMYL	11/08/1999	0.2 mg/L	0.001 mg/L	CXLP 19960701	
Not Detected	PROPOXUR (BAYGON)	11/08/1999		0.001 mg/L	CXLP 19960701	

Laboratory Comments and Result Notes:

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

P.O. Box 30270, Lansing, MI 48909

TEL: 517/335-8184 FAX: 517/335-8562

### Official Laboratory Report



Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Samule Number: C2000003094 Customer Number: 73654100

System Name/Owner:

City of Rockford

Collection Address:

10 East Bridge, Rockford 49341

Collected By:

**DENNIS BRINKS** 

Twp/Sec/Well #:

?/?/?

County:

Kent

Collector:

Public Water Supply Operator

Sample Kit #: Chlorination: 36**NV** 

Yes

WSSN / Pool ID: 5730

Sampled: 10/26/1999 2:35:00PM

Received: 10/27/1999 01:13PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Page: 1 of 1

Sample Point: PLANT LAB TAP

Site Code:

			Supplemental Information Related To Reported Result						
Test Result	Analyte Name		Tested	Health Limit MCL	Minimum Rpt. Limit	Test Code			
Not Detected	2,4,5-T	1	10/28/1999		0.001 mg/L	CXHB 19960701			
Not Detected	2,4,5-TP (SILVEX)	1	10/28/1999	0.05 mg/L	0.0003 mg/L	CXHB 19960701			
Not Detected	2,4-D	1	10/28/1999	0.07 mg/L	0.002 mg/L	CXHB 19960701			
Not Detected	ACIFLUORFEN	÷ t	10/28/1999		0.004 mg/L	CXHB 19960701			
Not Detected	BENTAZON	1	10/28/1999		0.002 mg/L	CXHB 19960701			
Not Detected	DICAMBA	! !	10/28/1999		0.002 mg/L	CXHB 19960701			
Not Detected	DINOSEB	i 1	10/28/1999	0.007 mg/L	0.0003 mg/L	CXHB 19960701			
Not Detected	PENTACHLOROPHENOL	1	10/28/1999	0.001 mg/L	0.00008 mg/L	CXHB 19960701			
Not Detected	PICLORAM	1 1	10/28/1999	0.5 mg/L	0.002 mg/L	CXHB 19960701			

Laboratory Comments and Result Notes:

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003

P.O. Box 30270, Lansing, MI 48909

TEL: 517/335-8184 FAX: 517/335-8562

### Official Laboratory Report

Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Nov 18, 1999

Sample Number: C2000003093

Customer Number: 73654100

System Name/Owner: City of Rockford

Collection Address: 10 East Bridge, Rockford 49341

Collected By: DENNIS BRINKS

Twp/Sec/Well #: ?/?/?

County: Kent

Collector: Public Water Supply Operator

Sample Kit #: 36NV

Chlorination: Yes

WSSN / Pool ID: 5730

Sampled: 10/26/1999 2:32:00PM Received: 10/27/1999 01:13PM

Source: Type I

Purpose: Routine Monitoring

Water System: Treated Public Distribution

Sample Point: PLANT LAB TAP

Site Code:

		Supplemental Information Related To Reported Result				
			Health	Minimum		
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code	
Not Detected	ALACHLOR	10/28/1999	0.002 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	ALDRIN	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	AMETRYN	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	ATRAZINE	10/28/1999	0.003 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	BROMACIL	10/28/1999		0.002 mg/L	CXPT 19960701	
Not Detected	BUTACHLOR	10/28/1999		0.002 mg/L	CXPT 19960701	
Not Detected	BUTYLATE	10/28/1999		0.002 mg/L	CXPT 19960701	
Not Detected	CARBOXIN	10/28/1999		0.002 mg/L	CXPT 19960701	
Not Detected	CHLORDANE, alpha	10/28/1999	0.002 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	CHLORDANE,gamma-	10/28/1999	0.002 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	CHLOROTHALONIL	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	CYANAZINE	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	CYCLOATE	10/28/1999		0.002 mg/L	CXPT 19960701	
Not Detected	CYPRAZINE	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	DACTHAL	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	DDD,4,4'-	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	DDE,4,4'-	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	DDT,4,4'-	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	DIELDRIN	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	DIPHENAMID	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	ENDOSULFAN, alpha	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	ENDOSULFAN,beta	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	ENDRIN	10/28/1999	0.002 mg/L	0.00005 mg/L	CXPT 19960701	
lot Detected	ENDRIN ALDEHYDE	10/28/1999	Č	0.001 mg/L	CXPT 19960701	
authority of F	PA 368 1978 as amended.	Process Batch #: 9111673	22   11/1	6/1999 12:33:28PM	Page: 1 of 2	

		Supplemental Information Related To Reported Result				
		1	Health	Minimum		
Test Result	Analyte Name	Tested	Limit MCL	Rpt. Limit	Test Code	
Not Detected	EPTAM	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	HEPTACHLOR	10/28/1999	0.0004 mg/L	0.00008 mg/L	CXPT 19960701	
Not Detected	HEPTACHLOR EPOXIDE	10/28/1999	0.0002 mg/L	0.00004 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROBENZENE	10/28/1999	0.001 mg/L	0.0001 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROCYCLOHEXANE	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROCYCLOHEXANE (BETA-BHC)	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROCYCLOHEXANE	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	HEXACHLOROCYCLOPENTADIENE	10/28/1999	0.05 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	HEXAZINONE	10/28/1999		0.003 mg/L	CXPT 19960701	
Not Detected	LINDANE (GAMMA-BHC)	10/28/1999	0.0002 mg/L	0.00004 mg/L	CXPT 19960701	
Not Detected	METHOXYCHLOR	10/28/1999	0.04 mg/L	0.0002  mg/L	CXPT 19960701	
Not Detected	METOLACHLOR	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	METRIBUZIN	10/28/1999		$0.001~\mathrm{mg/L}$	CXPT 19960701	
Not Detected	OCTACHLOROCYCLOPENTENE	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1016)	10/28/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1221)	10/28/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1232)	10/28/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1242)	10/28/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1248)	10/28/1999	0.0005 mg/L	$0.0002~\mathrm{mg/L}$	CXPT 19960701	
Not Detected	PCB (AROCLOR 1254)	10/28/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	PCB (AROCLOR 1260)	10/28/1999	0.0005 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	POLYBROMINATED BIPHENYLS	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	PROMETON	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	PRONAMIDE	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	PROPACHLOR	10/28/1999		0.003 mg/L	CXPT 19960701	
Not Detected	PROPAZINE	10/28/1999		0.001 mg/L	CXPT 19960701	
Not Detected	SIMAZINE	10/28/1999	0.004 mg/L	0.0002 mg/L	CXPT 19960701	
Not Detected	TEBUTHIURON	10/28/1999		$0.005~\mathrm{mg/L}$	CXPT 19960701	
Not Detected	TERBACIL	10/28/1999		0.002 mg/L	CXPT 19960701	
Not Detected	TOXAPHENE	10/28/1999	0.003 mg/L	0.002 mg/L	CXPT 19960701	
Not Detected	TRIFLURALIN	10/28/1999		0.001 mg/L	CXPT 19960701	

Laboratory Comments and Result Notes:

DWRP Laboratory Services - Drinking Water Lab USEPA Region V Drinking Water Lab Cert. No. MI00003 P.O. Box 30270, Lansing, MI 48909

TEL: 517/335-8184 FAX: 517/335-8562

## Official Laboratory Report

DATE 1/24/00

Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

River Still

Sample Number: C2000008455 Customer Number: 73654100

City of Rockford WSSN / Pool ID: 5730 System Name/Owner:

Collection Address: 10 East Bridge, Rockford 49341 Sampled: 12/10/1999 11:00:00AM Received: 12/13/1999 02:17PM

**KURT MALZAHN** Collected By:

Twp/Sec/Well #: ?/?/? Source: Type I

Purpose: Routine Monitoring County: Kent

Water System: Treated Public Distribution Collector: Public Water Supply Operator

Sample Kit #: 36VO Sample Point: LAB TAP

Chlorination: Yes Site Code:

Test Result		Supplemental Information Related To Reported Result			
	Analyte Name	Tested	Health Limit MCL	Minimum Rpt. Limit	Test Cod
Not Detected	BENZENE	12/22/1999	0.005 mg/L	0.0005 mg/L	CXVO 1996070
Not Detected	BROMOBENZENE	12/22/1999		0.0005  mg/L	CXVO 1996070
Not Detected	BROMOCHLOROMETHANE	12/22/1999		0.0005 mg/L	CXVO 1996070
Not Detected	BROMOFORM	12/22/1999	0.10 mg/L	0.0004 mg/L	CXVO 1996070
Not Detected	BROMOMETHANE	12/22/1999		0.020  mg/L	CXVO 1996070
Not Detected	BUTYLBENZENE, NORMAL-	12/22/1999		0.0005~mg/L	CXVO 1996070
Not Detected	BUTYLBENZENE, SEC-	12/22/1999		0.0005 mg/L	CXVO 1996070
Not Detected	BUTYLBENZENE, TERT-	12/22/1999		0.0005  mg/L	CXVO 19960701
Not Detected	CARBON TETRACHLORIDE	12/22/1999	0.005  mg/L	0.0004  mg/L	CXVO 19960701
Not Detected	CHLOROBENZENE	12/22/1999	0.1  mg/L	0.0005  mg/L	CXVO 19960701
Trace	CHLORODIBROMOMETHANE	: 12/22/1999	0.10  mg/L	0.0004  mg/L	CXVO 19960701
Not Detected	CHLOROETHANE	12/22/1999		0.020~mg/L	CXVO 19960701
0.0235 mg/L	CHLOROFORM	12/22/1999	0.10  mg/L	0.0004  mg/L	CXVO 19960701
Not Detected	CHLOROMETHANE	12/22/1999		$0.05\ mg/L$	CXVO 19960701
Not Detected	CHLOROTOLUENE (COMBINED)	: 12/22/1999		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	DIBROMO-3-CHLOROPROPANE, 1,2-	12/22/1999		0.0025~mg/L	CXVO 19960701
Not Detected	DIBROMOETHANE 1,2- (EDB)	12/22/1999		0.0005  mg/L	CXVO 19960701
Not Detected	DIBROMOMETHANE	12/22/1999		0.0005 mg/L	CXVO 19960701
Not Detected	DICHLOROBENZENE,1,2-	12/22/1999	0.6 mg/L	0.0005~mg/L	CXVO 19960701
Not Detected	DICHLOROBENZENE,1,3-	: 12/22/1999		0.0004 mg/L	CXVO 19960701
Not Detected	DICHLOROBENZENE,1,4-	12/22/1999	0.075 mg/L	0.0004 mg/L	CXVO 19960701
0.0027 mg/L	DICHLOROBROMOMETHANE	12/22/1999	0.10 mg/L	0.0004 mg/L	CXVO 19960701
Not Detected	DICHLOROBUTANE, 1,4-	12/22/1999	_	0.0005 mg/L	CXVO 19960701
Not Detected	DICHLORODIFLUOROMETHANE	12/22/1999		0.001 mg/L	CXVO 19960701
Not Detected	DICHLOROETHANE,1,1-	12/22/1999		0.0005 mg/L	CXVO 19960701

By authority of PA 368 1978 as amended.

Process Batch #: 0012131

| 135 | 01/21/2000 11:16:02AM

Page: 1 of 2

		Su	Supplemental Information Related To Reported Result				
Test Result	Analyte Name	Tested	Health Limit MCL	Minimum Rpt. Limit	Test Code		
Not Detected	DICHLOROETHANE,1,2-	12/22/1999	0.005 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	DICHLOROETHYLENE,1,1-	12/22/1999	0.007 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	DICHLOROETHYLENE,1,2-CIS	12/22/1999	0.07 mg/L	0.0004 mg/L	CXVO 19960701		
Not Detected	DICHLOROETHYLENE,1,2-TRANS	12/22/1999	0.1 mg/L	0.0004 mg/L	CXVO 19960701		
Not Detected	DICHLOROPROPANE,1,2-	: 12/22/1999	0.005 mg/L	0.0004 mg/L	CXVO 19960701		
Not Detected	DICHLOROPROPANE,1,3-	12/22/1999	, , ,	0.001 mg/L	CXVO 19960701		
Not Detected	DICHLOROPROPANE,2,2-	12/22/1999		0.001 mg/L	CXVO 19960701		
Not Detected	DICHLOROPROPENE,1,1-	12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	DICHLOROPROPENE,1,3-CIS	12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	DICHLOROPROPENE,1,3-TRANS	: 12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	ETHYLBENZENE	12/22/1999	0.7 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	FLUOROTRICHLOROMETHANE	12/22/1999	Č	0.001 mg/L	CXVO 19960701		
Not Detected	HEXACHLOROBUTADIENE	12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	HEXACHLOROETHANE	12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	ISOPROPYL BENZENE	12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	ISOPROPYL TOLUENE, PARA-	12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	METHYL ETHYL KETONE	12/22/1999		0.02 mg/L	CXVO 19960701		
Not Detected	METHYL ISOBUTYL KETONE	12/22/1999		0.02 mg/L	CXVO 19960701		
Not Detected	METHYL TERT-BUTYL ETHER	12/22/1999		0.001 mg/L	CXVO 19960701		
Not Detected	METHYLENE CHLORIDE	12/22/1999	0.005 mg/L	0.0006 mg/L	CXVO 19960701		
Not Detected	NAPHTHALENE	12/22/1999		0.001 mg/L	CXVO 19960701		
Not Detected	PROPYLBENZENE, NORMAL-	12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	STYRENE	12/22/1999	0.1 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	TETRACHLOROETHANE,1,1,1,2-	12/22/1999	S	0.0005 mg/L	CXVO 19960701		
Not Detected	TETRACHLOROETHANE,1,1,2,2-	12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	TETRACHLOROETHYLENE	12/22/1999	0.005 mg/L	0.0004 mg/L	CXVO 19960701		
Not Detected	TETRAHYDROFURAN	12/22/1999	J	0.005 mg/L	CXVO 19960701		
Not Detected	TOLUENE	12/22/1999	1 mg/L	0.0005 mg/L	CXVO 19960701		
0.0362 mg/L	TOTAL TRIHALOMETHANES	12/22/1999	0.10 mg/L	0.0004 mg/L	CXVO 19960701		
Not Detected	TRICHLOROBENZENE,1,2,3-	12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	TRICHLOROBENZENE,1,2,4-	12/22/1999	0.07 mg/L	0.0005  mg/L	CXVO 19960701		
Not Detected	TRICHLOROETHANE,1,1,1-	12/22/1999	0.2 mg/L	0.0004 mg/L	CXVO 19960701		
Not Detected	TRICHLOROETHANE,1,1,2-	12/22/1999	0.005 mg/L	0.0005  mg/L	CXVO 19960701		
Not Detected	TRICHLOROETHYLENE	12/22/1999	0.005 mg/L	0.0004 mg/L	CXVO 19960701		
Not Detected	TRICHLOROPROPANE,1,2,3-	12/22/1999		0.0005  mg/L	CXVO 19960701		
Not Detected	TRIMETHYLBENZENE,1,2,4-	12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	TRIMETHYLBENZENE,1,3,5-	12/22/1999		0.0005 mg/L	CXVO 19960701		
Not Detected	VINYL CHLORIDE	12/22/1999	0.002 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	XYLENE, ORTHO-	12/22/1999	10 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	XYLENE,META-&PARA-	12/22/1999	10 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	XYLENES (TOTAL)	12/22/1999	10 mg/L	0.0005 mg/L	CXVO 19960701		
				=			

Laboratory Comments and Result Notes:

Compounds reported as TRACE were detected at levels above the detection limits, but at levels too low to quantitate.

Drinking Water Laboratory - DWRP Division

3500 N. M.L. King Blvd. Lansing MI 48909

517/335-8184

RECEIVED PER 2 3 1998

## Official Laboratory Report

Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

Sample Number: C1998018024 Customer Number: 73654100

System Name/Owner

City of Rockford

WSSN / Pool ID: 5730

Collection Address:

10 3 Bridge Street, Rockford 49341

Sampled: 02/11/1998 1:15:00PM

Collected By: Ro

ROGER LINDER

Received: 02/12/1998 01:26PM

Twp/Sec/Well #:

?/?/?

Yes

Source: Type I

Sample Point: PLANT TAP

County: Kent

Kent

Purpose: Routine Monitoring

Collector: Pr

Public Water Supply Operator

Water System: Pressure Tank/Plant Tap

Page: 1 of 1

Sample Kit #: 32

Chlorination:

Site Code:

		Su	ion Related To Repor	ted Result	
			Health	Minimum	
Test Result	Analyte Name	Tested	Limit MCL	Rpt	Test Code
31 mg/L	CHLORIDE (AUTOMATED)	02/18/1998		4 mg/L	CRA 19960701
1.0 mg/L	FLUORIDE (AUTOMATED)	02/18/1998	4.0 mg/L	$0.1~{ m mg/L}$	CRA 19960701
172 mg/L	HARDNESS AS CaCO3	02/18/1998		10 mg/L	CRA 19960701
Not Detected	IRON (AUTOMATED)	02/18/1998		0.1 mg/L	CRA 19960701
1.7 mg/L	NITRATE AS N (AUTOMATED)	02/18/1998	10 mg/L	$0.4~\mathrm{mg/L}$	CRA 19960701
Not Detected	NITRITE AS N (AUTOMATED)	02/18/1998	1 mg/L	0.05 mg/L	CRA 19960701
20 mg/L	SODIUM (AUTOMATED)	02/18/1998		5 mg/L	CRA 19960701
89 mg/L	SULFATE (AUTOMATED)	02/18/1998		5 mg/L	CRA 19960701

Laboratory Comments and Result Notes: None

Drinking Water Laboratory - DWRP Division

" RECEIVED MAR 1 0 1898

3500 N. M.L. King Blvd. Lansing MI 48909

517/335-8184

## **Official Laboratory Report**

Report To:

City of Rockford Water Plant

7 South Monroe

PO Box 561

Rockford MI 49341

System Name/Owner

Sample Number: C1998018071 Customer Number: 73654100

CITY OF ROCKFORD WSSN / Pool ID: 5730

Collection Address: 10 E. Bridge St., Rockford 49341 Sampled: 02/11/1998 1:15:00PM

Collected By: ROGER LINDER Received: 02/12/1998 02:00PM

Twp/Sec/Well #: ?/?/? Source: Type I

County: Kent Purpose: Routine Monitoring

Collector: Public Water Supply Operator Water System: Pressure Tank/Plant Tap

Sample Kit #: 36VO Sample Point: PLANT TAP

Chlorination: Yes Site Code:

Chlorination: Yes			Site Code.				
		Sı	Supplemental Information Related To Reported Result				
			Health	Minimum			
Test Result	Analyte Name	Tested	Limit MCL	Rpt.	Test Code		
'Not Detected	BENZENE ·	02/22/1998	0.005 mg/L	0.0005 mg/L	CXVO 19960701		
Not Detected	BROMOBENZENE	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	BROMOCHLOROMETHANE	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701		
"Not Detected	BROMOFORM	02/22/1998	0.10 mg/L	$0.0004~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	BROMOMETHANE	02/22/1998		0.020 mg/L	CXVO 19960701		
Not Detected	BUTYLBENZENE. NORMAL-	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	BUTYLBENZENE. SEC-	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	BUTYLBENZENE. TERT-	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701		
/ Not Detected	CARBON TETRACHLORIDE*	02/22/1998	0.00 <u>5 mg/L</u>	$0.0004~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	CHLOROBENZENE ~	02/22/1998	0.1 mg/L	0.0005 mg/L	CXVO 19960701		
√0.0006 mg/L	CHLORODIBROMOMETHANE	02/22/1998	0.10  mg/L	$0.0004~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	CHLOROETHANE	02/22/1998		$0.020~\mathrm{mg/L}$	CXVO 19960701		
<b>√</b> 0.0115 mg/L	CHLOROFORM	02/22/1998	0.10  mg/L	$0.0004~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	CHLOROMETHANE	02/22/1998		$0.05~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	CHLOROTOLUENE (COMBINED)	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	DIBROMO-3-CHLOROPROPANE.	1.2- 02/22/1998	•	$0.0025~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	DIBROMOETHANE 1.2- (EDB)	02/22/1998		0.0005  mg/L	CXVO 19960701		
Not Detected	DIBROMOMETHANE	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701		
≤ Not Detected	DICHLOROBENZENE.1.2-	02/22/1998	0.6 mg/L	$0.0005~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	DICHLOROBENZENE.1.3-	02/22/1998		$0.0004~\mathrm{mg/L}$	CXVO 19960701		
<b>X</b> Not Detected	DICHLOROBENZENE.1.4-	02/22/1998	0.075  mg/L	$0.0004  \mathrm{mg/L}$	CXVO 19960701		
₹0.0025 mg/L	DICHLOROBROMOMETHANE	02/22/1998	0.10  mg/L	$0.0004~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	DICHLOROBUTANE. 1.4-	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	DICHLORODIFLUOROMETHANE	02/22/1998		0.001 mg/L	CXVO 19960701		
Not Detected	DICHLOROETHANE.1.1-	02/22/1998		0.0005  mg/L	CXVO 19960701		
√Not Detected	DICHLOROETHANE.1.2-	02/22/1998	0.005 mg/L	0.0005 mg/L	CXVO 19960701		
₩Not Detected	DICHLOROETHYLENE.1.1-~	02/22/1998	0.007 mg/L	$0.0005~\mathrm{mg/L}$	CXVO 19960701		
<sup>⊀</sup> Not Detected	DICHLOROETHYLENE.1.2-CIS >	02/22/1998	0.07  mg/L	$0.0004~\mathrm{mg/L}$	CXVO 19960701		
Not Detected	DICHLOROETHYLENE, 1.2-TRANS	02/22/1998	0.1 mg/I,	0.0004  mg/L	CXVO 19960701		
√Not Detected	DICHLOROPROPANE.1.2-	02/22/1998	0.005 mg/L	0.0004 mg/L	CXVO 19960701		
By authority of I	PA 368 1978 as amended.	Process Batch #: 8030448	1 113   03/0	4/1998 02:58:24PN	A Page: 1 of 2		

		Sı	ipplemental Informat	ion Related To Repo	orted Result
			Health	Minimum	
Test Result	Analyte Name	Tested	Limit MCL	Rpt.	Test Code
Not Detected	DICHLOROPROPANE.1.3-	02/22/1998		0.001 mg/L	CXVO 19960701
Not Detected	DICHLOROPROPANE.2.2-	02/22/1998		$0.001~\mathrm{mg/L}$	CXVO 19960701
Not Detected	DICHLOROPROPENE.1.1-	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	DICHLOROPROPENE.1.3-CIS	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	DICHLOROPROPENE.1.3-TRANS	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701
⋆Not Detected	ETHYLBENZENE	02/22/1998	$0.7~\mathrm{mg/L}$	$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	FLUOROTRICHLOROMETHANE	02/22/1998		0.001 mg/L	CXVO 19960701
Not Detected	HEXACHLOROBUTADIENE	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	HEXACHLOROETHANE	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	ISOPROPYL BENZENE	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	ISOPROPYL TOLUENE. PARA-	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	METHYL ETHYL KETONE	02/22/1998		$0.02~\mathrm{mg/L}$	CXVO 19960701
Not Detected	METHYL ISOBUTYL KETONE	02/22/1998		$0.02~{ m mg/L}$	CXVO 19960701
Not Detected	METHYL TERT-BUTYL ETHER	02/22/1998		$0.001~\mathrm{mg/L}$	CXVO 19960701
✓ Not Detected	METHYLENE CHLORIDE	02/22/1998	$0.005~\mathrm{mg/L}$	$0.0006~\mathrm{mg/L}$	CXVO 19960701
Not Detected	NAPHTHALENE	02/22/1998		$0.001~\mathrm{mg/L}$	CXVO 19960701
Not Detected	PROPYLBENZENE. NORMAL-	02/22/1998		0.0005 mg/L	CXVO 19960701
✓ Not Detected	STYRENE *	02/22/1998	0.1  mg/L	$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	TETRACHLOROETHANE.1.1.1.2-	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	TETRACHLOROETHANE.1.1.2.2-	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701
<sup> </sup>	TETRACHLOROETHYLENE"	02/22/1998	$0.005~\mathrm{mg/L}$	0.0004 mg/L	CXVO 19960701
Not Detected	TETRAHYDROFURAN	02/22/1998		$0.005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	TOLUENE '	02/22/1998	1 mg/L	$0.0005~\mathrm{mg/L}$	CXVO 19960701
^ 0.0146 mg/L	TOTAL TRIHALOMETHANES	02/22/1998	$0.10~\mathrm{mg/L}$	$0.0004~{ m mg/L}$	CXVO 19960701
Not Detected	TRICHLOROBENZENE.1.2.3-	02/22/1998		$0.0005~{ m mg/L}$	CXVO 19960701
<ul> <li>Not Detected</li> </ul>	TRICHLOROBENZENE.1.2.4-V	02/22/1998	$0.07~\mathrm{mg/L}$	$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	TRICHLOROETHANE.1.1.1- ✓	02/22/1998	$0.2~{ m mg/L}$	$0.0004~\mathrm{mg/L}$	CXVO 19960701
' Not Detected	TRICHLOROETHANE.1.1.2-	02/22/1998	0.005 mg/L	0.0005 mg/L	CXVO 19960701
'Not Detected	TRICHLOROETHYLENE *	02/22/1998	$0.005~\mathrm{mg/L}$	$0.0004~\mathrm{mg/L}$	CXVO 19960701
Not Detected	TRICHLOROPROPANE.1.2.3-	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	TRIMETHYLBENZENE.1.2.4-	02/22/1998		0.0005 mg/L	CXVO 19960701
Not Detected	TRIMETHYLBENZENE.1.3.5-	02/22/1998		$0.0005~\mathrm{mg/L}$	CXVO 19960701
Not Detected	VINYL CHLORIDE ~	02/22/1998	$0.002~\mathrm{mg/L}$	$0.0005~\mathrm{mg/L}$	CXVO 19960701
√ Not Detected	XYLENE. ORTHO- >	02/22/1998	10 mg/L	$0.0005~\mathrm{mg/L}$	CXVO 19960701
x Not Detected	XYLENE.META-&PARA-	02/22/1998	10 mg/L	$0.0005~\mathrm{mg/L}$	CXVO 19960701
/ Not Detected	XYLENES (TOTAL)	02/22/1998	10 mg/L	$0.0005~\mathrm{mg/L}$	CXVO 19960701

Laboratory Comments and Result Notes: None

Laboratory report for sample : C97015874 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE

City: ROCKFORD HI 49341

TWP-SEC/Key**≹:** 

County: KENT

RECEIVED MAR 2 4 1997

CITY OF ROCKFORD P.O. BOX 561 ROCKFORD MI 49341 7

WSSN/Pool# : 5730

Approved: JR

Collected: 03/13/97 15:15

Entered: 03/18/97

Chlorinated: YES

Sample unit: 32

Collector: DICK JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP
Point description: PLANT TAP WELL#:

Site:

ANALYTE	RESULT	DATE TESTED	CONTAMINANT LEVEL	TEST	DETECTION LIMIT
NITRATE AS N (AUTOMATED)	1.4 ng/L	03/20/97 15:07	10 mg/L	CRA	0.2 mg/L
NITRITE AS N (AUTOMATED)	NOT DETECTED	03/20/97 01:30	1 mg/L	CRA	0.02 mg/L
CHLORIDE (AUTOMATED)	29 mg/L	03/20/97 14:52	_	CRA	2 mg/L
FLUORIDE (AUTOMATED)	1.0 mg/L	03/20/97 01:30	4.0 mg/L	CRA	0.1 mg/L
HARDNESS AS C⊴CO3	140 mg/L	03/20/97 11:22	-	CRA	10 mg/L
IRON (AUTOMATED)	NOT DETECTED	03/20/97 11:22		CRA	0.1 mg/L
SULFATE (AUTOMATED)	70 mg/L	03/20/97 14:41		CRA	2 mg/L
SODIUH (AUTOHATED)	10 mg/L	03/20/97 11:22		CRA	2 mg/L

By authority of PA 368 1978 as amended

Printed: 03/21/97 01:52:58

PAGE 01 (END OF REPORT)

Laboratory report for sample : C97015854 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE City: ROCKFORD MI 49341 TUP-SEC/Key#:

UF-SEC/Key#: County: KENT

> CITY OF ROCKFORD P.O. BOX 541 ROCKFORD HI 49341



WSSN/Pool# : 5730 Approved: SGK

Collected: 03/13/97 15:15 Entered: 03/18/97

Chlorinated: YES Sample unit:

Collector: KURT MALZAHN

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING
Point code: (7) PRESSURE TANK/PLANT TAP
Point description: PLANT TAP
WELL\*:

Site:

ntiáLYTE	RESULT	DATE TESTED	MAXIHUM CONTAMINANT LEVEL	TEST	DETECTION LIHIT
BRONOCHLORSMETHANE	HOT DETECTED	03/19/97 17:00		CXVO	0.0005 ng/L
BROHOFORH	HOT DETECTED	03/19/97 17:00	0.10 mg/L	CXVO	0.0002 mg/L
BROMOHETHANE	NOT DETECTED	03/19/97 17:00		CXVO	0.020 mg/L
CARBON TETRACHLORIDE	NOT DETECTED	03/19/97 17:00	0.005 ng/L	CXVO	0.0002 թ <u>գ</u> /L
CHLOROBENZENE	NOT DETECTED	03/19/97 17:00	0.1 mg/L	CXVO	0.0002 mg/L
CHLORODIBROHOMETHANE	0.0004 mg/L	03/19/97 17:00	0.10 mg/L	CXYO	<b>0.</b> 0002 mg/L
CHLOROETHANE	NOT DETECTED	03/19/97 17:00		CXVO	0.020 mg/L
CHLORGFORM	0.0231 mg/L	03/19/97 17:00	0.10 mg/L	CXVO	0.0002 mg/L
CHLOROHETHANE	HOT DETECTED	03/19/97 17:00	-	CXVO	0.05 ma/L
DIBROHOMETHANE	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 mg/L
DICHLOROBROMOHETHANE	0.0024 mg/L	03/19/97 17:00	0.10 mg/L	CXVO	0.0002 mg/L
DICHLORODIFLUGROMETHANE	NOT DETECTED	03/19/97 17:00	·	CXVO	0.001 mg/L
DICHLOROETHANE,1,1-	HOT DETECTED	03/19/97 17:00		CXVO	0.0005 ח∕L
DICHLOROETHANE,1,2-	NOT DETECTED	03/19/97 17:00	0.005 mg/L	CXVO	0.0002 mg/L
DICHLOROETHYLENE,1,1-	NOT DETECTED	03/19/97 17:00	0.007 mg/L	CXVO	0.0002 na/L
DICHLOROETHYLEHE,1,2-CIS	NOT DETECTED	03/19/97 17:00	0.07 mg/L	CXVO	0.0 <mark>00</mark> 2 mg/L
DICHLOROETHYLENE,1,2-TRANS	NOT DETECTED	03/19/97 17:00	0.1 mg/L	CXVO	0.0002 ma/L
DICHLOROPROPAME,1,2-	NOT DETECTED	03/19/97 17:00	0.005 mg/L	CXVO	0.0002 mg/L
DICHLOROPROPANE,1,3-	NOT DETECTED	03/19/97 17:00		CXVO	0.001 mg/L
DICHLOROPROPANE.2,2-	NOT DETECTED	03/19/97 17:00		CXVO	0.001 ng/L
BICHLOROPROPENE,1,1-	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 ng/L
DIGROMOETHANE 1,2- (EDB)	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 mg/L
FLUORCTRICHLOROMETHANE	NOT DETECTED	03/19/97 17:00		GVVD	0.00i mg/L
HEXACHLOROBUTADIENE	HOT DETECTED	03/19/97 17:00		CXVO	0.0005 ag/L
HEXACHLOROETHANE	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 mg/L
METHYLENE CHLORIDE	NOT DETECTED	03/19/97 17:00	0.005 mg/L	CXVO	0.0003 mg/L
TETRACHLORGETHANE,1,1,1,2-	NOT DETECTED	03/19/97 17:00	.3	CXVO	0.0005 mg/L
TETRACHLOROETHANE.1,1,2.2-	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 mg/L
TETRACHLOROETHYLENE	NOT DETECTED	03/19/97 17:00	0.005 mg/L	CXVO	0.0002 mg/L
TUTAL TRIHALOMETHANES	0.0261 mg/L	03/19/97 17:00	0.10 mg/L	CXVO	0.0002 mg/L
TRICHLOROETHANE,1,1,1-	NOT DETECTED	03/19/97 17:00	0.2 mg/L	CXVO	0.0002 mg/L
TRICHLOROETHANE,1,1,2-	NOT DETECTED	03/19/97 17:00	0.005 mg/L	CXVO	0.0004 mg/L
TRICHLOROETHYLENE	HOT DETECTED	03/19/97 17:00	0.005 mg/L	CXVO	0.0002 ma/L
TRICHLOROPROPANE,1,2,3-	NOT DETECTED	03/19/97 17:00	\\ <del>\\</del>	CXVO	0.0005 mg/L
DICHLOROPROPENE,1,3-CI3	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 mg/L
DICHLOROPROPENE,1.3-TRANS	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 ag/L
VINYL CHLORIDE	NOT DETECTED	03/19/97 17:00	0.002 mg/L	CXVO	0.0003 mg/L
BENZEHE	HOT DETECTED	03/19/97 17:00	0.002 mg/L	CXVO	0.0003 MB/L 0.0002 Mg/L
BROHOBENZENE	HOT DETECTED	03/19/97 17:00	A.AAG NAVE	CXAO	-
DNUNUBERZERE	RUI DETECTED	V3/17/7/ 1/ <b>:V</b> 0		FYAR	0.0005 mg/L

Laboratory report for sample : 097015854 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE City: ROCKFORD HI 49341

TWP-SEC/Key**#:** County: KENT

> CITY OF ROCKFORD P.O. BOX 561 ROCKFORD HI 49341

WSSN/Pool\*: 5730 Approved: SGK

Collected: 03/13/97 15:15 Entered: 03/18/97 Chlorinated: YES

Sample unit:

Collector: KURT MALZAHN

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP Point description: PLANT TAP WELL#:

Site:

AMALYTE	RESULT	DATE TESTED	MAXIHUM CONTAMINANT LEVEL	TEST	DETECTION LIMIT
BUTYLBENZENE, TERT-	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 mg/L
BUTYLBENZENE, SEC-	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 mg/L
BUTYLBENZENE, NORMAL-	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 rig/L
CHLORGTOLUENE (COMBINED)	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 mg/L
DIBROHO-3-CHLOROPROPANE, 1,2-	NOT DETECTED	03/19/97 17:00		CXVO	0.0025 mg/L
DICHLOROBUTANE, 1,4-	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 mg/L
DICHLOROBENZEHE,1,4-	NOT DETECTED	03/19/97 17:00	0.075 mg/L	CXVO	0.0002 mg/L
DICHLOROBENZENE,1,3-	NOT DETECTED	03/19/97 17:00	•	CXVO	0.0002 mg/L
DICHLOROBENZENE,1,2-	NOT DETECTED	03/19/97 17:00	0.6 mg/L	CXVO	0.0005 ma/L
ETHYLBENZENE	MOT DETECTED	03/19/97 17:00	0.7 mg/L	CXVO	0.0002 mg/L
HETRYL ETHYL KETONE	NOT DETECTED	03/19/97 17:00	-	CXVO	0.02 mg/L
HETHYL ISOBUTYL KETONE	NOT DETECTED	03/19/97 17:00		CXAO	0.02 mg/L
WAPHTWALENE	NOT DETECTED	03/19/97 17:00		CXVO	0.001 ma/L
ISOPROPYL BENZENE	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 ng/L
PROPYLBENZENE. HORHAL-	NOT DETECTED	03/19/97 17:00		CXVO	0.0005 ma/L
STYREHE	NOT DETECTED	03/19/97 17:00	0.1 mg/L	CXVO	0.0005 mg/L
TOLUENE	NOT DETECTED	03/19/97 17:00	i mg/L	CXAO	0.0002 mg/L
ISOPROPYL TOLUENE, FARA-	NOT DETECTED	03/19/97 17:00	*	CXVO	0.0005 mg/L
TRICHLOROBENZENE,1,2,4-	HOT DETECTED	03/19/97 17:00	0.07 ma/L	CXVO	0.0002 ma/L
TRICHLOROBENZENE,1.2,3-	NOT DETECTED	03/19/97 17:00	·	CXVO	0.0005 mg/L
TRIHETHYLBENZENE,1,2,4-	NOT DETECTED	03/19/97 17:00		CXVD	0.0005 mg/L
TRIMETHYLBENZENE,1.3,5-	NOT DETECTED	03/19/97 17:00		CXVO	0.00 <b>0</b> 5 ag/L
XYLENE, META-&PARA-	NOT DETECTED	03/19/97 17:00	10 ma/L	CXVO	0.0005 ma/L
XYLENE, ORTHO-	NOT DETECTED	03/19/97 17:00	10 mg/L	CXVO	0.0005 mg/L
XYLENES (TOTAL)	NOT DETECTED	03/19/97 17:00	10 mg/L	CXVO	0.0005 mg/L
METHYL TERT-BUTYL ETHER	HOT DETECTED	03/19/97 17:00	•	CXVO	0.001 mg/L
TETRAHYDROFURAN	NOT DETECTED	03/19/97 17:00		CXVO	0.005 mg/L
authority of PA 368 1978 as amended		Printed : 00	3/28/97 01:41: <b>3</b> 9	PAGE 02	(END OF REPORT)

#### - வி

## OHIO DEPARTMENT OF HEALTH DIVISION OF LABORATORIES

## RADS, THM and SOC Sample Submission Report

1571 Perry Street	Laboratory Na	me: ODH Lab						
P.O. Box 2568	•	umber: (47) 1 2 3 4 5 (51)						
Columbus, Ohio 43266-0068								
	· · · · · · · · · · · · · · · · · · ·	Campio itamican (CI)						
	Analyst: <u></u>	eve Fonseca	<del></del>					
	Date Received	l: 9/23/97 Date Reported: (27)	nth Day Year					
	Sample Ide	ntification						
100 11 1110 1115	<u> </u>							
PWSID: (1) MICHIGAN WISH: 5	730 ] (7)	Sample Date Time (Use Milita	ry Time)					
Water Supply Name: City of The			linute					
Water Supply Name:	1 K tovol							
Address: 10 tast Pridge S-	+ ,	(36) (41) (43)	(46)					
City & Zip: Kock I. & UTII	49341	Sample Collected By: Rogar L	indir					
County: $\cancel{U}_{\sim} \perp$ Phone: (616) _	166-0560	Sample Location: Wales Via	<u>~</u>					
<del></del>		ks—Non Routine Analytical Requests						
	NaOH ☐ HNO <sub>3</sub>	•						
$\square$ Na <sub>2</sub> O <sub>3</sub> S <sub>2</sub> $\square$ CuSO <sub>4</sub> + H <sub>3</sub> PO <sub>4</sub> $\square$	•	(Explain) # 6/4 644	-4637					
	1	· · · · · · · · · · · · · · · · · · ·	, ,					
Sample Type (Raw-R, Plant-P, Dist-D)	<u> </u>	☐ Endothall ☐ Endrin	2033, .					
☐ Sample Type (Check-C, Special-S) ☐ Entry Point ID	<u> </u>	☐ Glyphosate	2005,					
RADIO ISOTOPES (RADS) pc/l	<u> </u>	☐ Heptachlor	2065.					
Q Alpha, Total	4000, <3	☐ Heptachlor Epoxide	2067.					
□ Alpha, Diss	4040,	☐ Hexachlorobenzene	2274,					
☐ Alpha, Suspd	4041, ,	☐ Hexachlorocyclopentadiene	2042,					
D Beta, Total	4100, 4.2	☐ Lindane	2010,					
□ Beta, Diss	4042,	Methoxychlor	2015,					
☐ Beta, Suspd	4043, .	Oxamyl (Vydate)     PAH's (benzo-a-pyrene)	2036,					
☐ Barium 140 ☐ Cesium-134	4270,	□ PCB's (total)	2306,					
Cesium-137	4276,	☐ Aroclor 1016	2388,					
□ lodine-131	4264	☐ Aroclor 1221	2390.					
☐ Potassium-40	4044, ,	☐ Aroclor 1232	2392,					
☐ Radium-226	4020	☐ Aroclor 1242	2394,					
Radium-228	4030,	☐ Aroclor 1248	2396, ,					
Radon-222	4004,	Arcelor 1254	2398,					
☐ Strontium-90 ☐ Strontium-89	4174,	☐ Aroclor 1260 ☐ Pentachlorophenol	2400, ,					
☐ Tritium	4102,	Adipates (di-2-ethylhexyladipate)	2035,					
Combined Uranium	4006,	☐ Phthalates (di-2-ethylhexylphthalate)	2039.					
Uranium-234	4007,	☐ Picloram	2040,					
□ Uranium-235	4008, ,	☐ Simazine	2037, ,					
Uranium-238	4009,	☐ Toxaphene	2020, ,					
TRIHALOMETHANES (THMs) ug/l	1	□ 2,4·D	2105,					
Chloroform	2941,	2,4,5-TP (Silvex)	2110, ,					
☐ Bromoform ☐ Bromodichloromethane	2942, , 2943	2,3,7,8-TCDD (Dioxin)     Metolachlor	2063, , 2045, ,					
☐ Dibromochloromethane	2944,	☐ Epichlorohydrin	2257.					
PESTICIDES AND OTHER ORGANIC CHEMICAL		☐ Acrylamide	2265,					
☐ Alachlor	2051, ,	☐ Acrolein	2238,					
☐ Aldicarb	2047, ,	☐ Acrylonitrile	2240,					
☐ Aldicarb Sulfoxide	2043,	☐ Cyanazine	2054, ,					
☐ Aldicarb Sulfone	2044,	☐ Dicamba	2440, ,					
Atrazine	2050, ,	☐ Trifluralin	2055, ,					
Carbofuran	2046,		11					
Chlordane	2959,	0						
Dalapon Dibromochloropropane	2031, , 2931, ,		,					
Dinoseb	2041,							
☐ Diloseb☐ Diquat	2032,		, ,					
☐ Ethylene Dibromide	2946,	0	,					
==-y-=		**************************************	<del></del>					

Laboratory report for sample : C96020275 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE City: ROCKFORD MI 49341

> TWP-SEC/Key#: County: KENT

> > RICHARD R JOHNSTON P.O. BOX 561 ROCKFORD MI 49341

Approved: SGK

Collected: 03/20/96 13:20 Entered: 03/22/96

Chlorinated: YES Sample unit:

WSSN/Pool# : 5730

Collector: RICHARD R JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

RECEIVED
DATE 4/22/96 Purpose: (0) ROUTINE MONITORING Point code: (7) PRESSURE TANK/PLANT TAP

Point description: 7

WELL#:

Site:

CHLOROMETHANE	COVX3	RESULT  NOT DETECTED  NOT DETECTED  NOT DETECTED  NOT DETECTED  0.0006 mg/L  NOT DETECTED	DATE TESTED  04/03/96 18:00 04/03/96 18:00 04/03/96 18:00 04/03/96 18:00 04/03/96 18:00	MAXIMUM CONTAMINANT LEVEL  0.10 mg/L  0.005 mg/L  0.1 mg/L	TEST CXVO CXVO CXVO CXVO EXVO	DETECTION LIMIT 0.0005 mg/L 0.0002 mg/L 0.020 mg/L
BROMOCHLOROMETHANE BROMOFORM BROMOMETHANE CARBON TETRACHLORIDE CHLOROBENZENE CHLORODIBROMOMETHANE CHLOROETHANE CHLOROFORM CHLOROFORM CHLOROMETHANE		NOT DETECTED NOT DETECTED NOT DETECTED NOT DETECTED NOT DETECTED 0.0006 mg/L	04/03/96 18:00 04/03/96 18:00 04/03/96 18:00 04/03/96 18:00 04/03/96 18:00	0.10 mg/L 0.005 mg/L	CXVO CXVO CXVO	0.0005 mg/L 0.0002 mg/L 0.020 mg/L
BROMOFORM BROMOMETHANE CARBON TETRACHLORIDE CHLOROBENZENE CHLORODIBROMOMETHANE CHLOROFORM CHLOROFORM CHLOROMETHANE		NOT DETECTED NOT DETECTED NOT DETECTED NOT DETECTED 0.0006 mg/L	04/03/96 18:00 04/03/96 18:00 04/03/96 18:00 04/03/96 18:00	0.005 mg/L	CXVO	0.0002 mg/L 0.020 mg/L
BROMOMETHANE CARBON TETRACHLORIDE CHLOROBENZENE CHLORODIBROMOMETHANE CHLOROFORM CHLOROFORM CHLOROMETHANE	EXTH3	NOT DETECTED NOT DETECTED NOT DETECTED 0.0006 mg/L	04/03/96 18:00 04/03/96 18:00 04/03/96 18:00	0.005 mg/L	CXVO	0.020 mg/L
CARBON TETRACHLORIDE CHLOROBENZENE CHLORODIBROMOMETHANE CHLOROETHANE CHLOROFORM CHLOROMETHANE	EXTH3	NOT DETECTED NOT DETECTED 0.0006 mg/L	04/03/96 18:00 04/03/96 18:00	-		•
CHLOROBENZENE CHLORODIBROMOMETHANE CHLOROETHANE CHLOROFORM CHLOROMETHANE	ЕНТХЭ	NOT DETECTED 0.0006 mg/L	04/03/96 18:00	-	EXVO	
CHLORODIBROMOMETHANE CHLOROETHANE CHLOROFORM CHLOROMETHANE	EXTHI	0.0006 mg/L		0.1 ma/L	2	0.0002 mg/L
CHLOROETHANE CHLOROFORM CHLOROMETHANE	[HTX]	-	04/03/96 18:00	1147 14	CXVO	0.0002 mg/L
CHLOROFORM CHLOROMETHANE	EXTH3	NOT DETECTED		0.10 mg/L	CXVO	0.0002 mg/L
CHLOROMETHANE	EXTH3		04/03/96 18:00		CXVO	0.020 mg/L
		0.0191 mg/L	04/03/96 18:00	0.10 ng/L	CXVO	0.0002 mg/L
		NOT DETECTED	04/03/96 18:00		CXVO	0.05 mg/L
DIBROHOMETHANE		NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
DICHLOROBROMOMETHANE		0.0028 mg/L	04/03/96 18:00	0.10 mg/L	CXVO	0.0002 mg/L
DICHLORODIFLUOROMETHANE		NOT DETECTED	04/03/96 18:00		CXVO	0.001 mg/L
DICHLOROETHANE,1,1-		NOT DETECTED	04/03/96 18:00		CXA0	0.0005 mg/L
DICHLOROETHANE,1,2-		NOT DETECTED	04/03/96 18:00	0.005 mg/L	CXVO	0.0002 mg/L
DICHLOROETHYLENE,1,1-		NOT DETECTED	04/03/96 18:00	0.007 mg/L	CXVO	0.0002 mg/L
DICHLOROETHYLENE,1,2-CIS		HOT DETECTED	04/03/96 18:00	0.07 mg/L	CXVO	0.0002 mg/L
DICHLOROETHYLENE,1,2-TRANS		NOT DETECTED	04/03/96 18:00	0.1 mg/L	CXVO	0.0002 mg/L
DICHLOROPROPANE,1,2-		NOT DETECTED	04/03/96 18:00	0.005 mg/L	CXVO	0.0002 mg/L
DICHLOROPROPANE,1,3-		NOT DETECTED	04/03/96 18:00	-	CXVO	0.001 mg/L
DICHLOROPROPANE,2,2-		NOT DETECTED	04/03/96 18:00		CXVO	0.001 mg/L
DICHLOROPROPENE,1,1-		NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
DIBROMOETHANE 1,2- (EDB)		NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
FLUOROTRICHLOROMETHANE		NOT DETECTED	04/03/96 18:00		CXVO	0.001 mg/L
HEXACHLOROBUTADIENE		NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
HEXACHLOROETHANE		NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
METHYLENE CHLORIDE		NOT DETECTED	04/03/96 18:00	0.005 mg/L	CXVO	0.0003 mg/L
TETRACHLOROETHANE,1,1,1,2-		NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
TETRACHLOROETHANE,1,1,2,2-		NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
TETRACHLOROETHYLENE		NOT DETECTED	04/03/96 18:00	0.005 mg/L	CXVD	0.0002 mg/L
TOTAL TRIHALOMETHANES		0.0225 mg/L	04/03/96 18:00	0.10 mg/L	CXVO	0.0002 mg/L
TRICHLOROETHANE,1,1,1-		NOT DETECTED	04/03/96 18:00	0.2 mg/L	CXVO	0.0002 mg/L
TRICHLOROETHANE,1,1,2-		NOT DETECTED	04/03/96 18:00	0.005 mg/L	CXVO	0.0004 mg/L
TRICHLOROETHYLENE		NOT DETECTED	04/03/96 18:00	0.005 mg/L	CXVO	0.0002 mg/L
TRICHLOROPROPANE,1,2,3-		NOT DETECTED	04/03/96 18:00	-	CXVO	0.0005 mg/L
DICHLOROPROPENE,1,3-CIS		NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
DICHLOROPROPENE,1,3-TRANS		NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
VINYL CHLORIDE		NOT DETECTED	04/03/96 18:00	0.002 mg/L	CXVO	0.0003 mg/L
BENZENE		NOT DETECTED	04/03/96 18:00	0.005 mg/L	CXVO	0.0002 mg/L
BROMOBENZENE		NOT DETECTED	04/03/96 18:00	STOOD HIGH	CXVO	0.0005 mg/L

Laboratory report for sample : C96020275 System mame/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE

City: ROCKFORD MI 49341

TWP-SEC/Key#:

County: KENT

RICHARD R JOHNSTON P.O. BOX 561 ROCKFORD HI 49341

WSSN/Pool# : 5730

Approved: SGK

Collected: 03/20/96 13:20 Entered: 03/22/96

Chlorinated: YES Sample unit:

Collector: RICHARD R JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP

Point description: 7

WELL#:

Site:

ANALYTE	RESULT	DATE TESTED	MAXIMUM CONTAMINANT LEVEL	TEST	DETECTION LIHIT
BUTYLBENZENE, TERT-	NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
BUTYLBENZENE, SEC-	NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
BUTYLBENZENE, NORMAL-	NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
CHLOROTOLUENE (COMBINED)	NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
DIBROMO-3-CHLOROPROPANE, 1,2-	NOT DETECTED	04/03/96 18:00		CXVO	0.0025 mg/L
DICHLOROBUTANE, 1,4-	NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
DICHLOROBENZENE,1,4-	NOT DETECTED	04/03/96 18:00	0.075 mg/L	CXVO	0.0002 mg/L
DICHLOROBENZENE,1,3-	NOT DETECTED	04/03/96 18:00	•	CXVO	0.0002 mg/L
DICHLOROBENZENE,1,2-	NOT DETECTED	04/03/96 18:00	0.6 mg/L	CXVO	0.0005 mg/L
ETHYLBENZENE	NOT DETECTED	04/03/96 18:00	0.7 mg/L	CXVO	0.0002 mg/L
HETHYL ETHYL KETONE	NOT DETECTED	04/03/96 18:00		CXVO	0.02 mg/L
METHYL ISOBUTYL KETONE	NOT DETECTED	04/03/96 18:00		CXVO	0.02 mg/L
NAPHTHALENE	NOT DETECTED	04/03/96 18:00		CXVO	0.001 mg/L
ISOPROPYL BENZENE	NOT DETECTED	04/03/96 18:00		CXVO	0.0005 ag/L
PROPYLBENZENE, NORMAL-	NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
STYRENE	NOT DETECTED	04/03/96 18:00	0.1 mg/L	CXVO	0.0005 mg/L
TOLUENE	NOT DETECTED	04/03/96 18:00	1 mg/L	CXVO	0.0002 mg/L
ISOPROPYL TOLUENE, PARA-	NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
TRICHLOROBENZENE,1,2,4-	NOT DETECTED	04/03/96 18:00	0.07 mg/L	CXVO	0.0002 mg/L
TRICHLOROBENZENE,1,2,3-	NOT DETECTED	04/03/96 18:00	-	CXVO	0.0005 mg/L
TRIMETHYLBENZENE,1,2,4-	NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
TRIMETHYLBENZENE,1,3,5-	NOT DETECTED	04/03/96 18:00		CXVO	0.0005 mg/L
XYLENE,META-&PARA-	NOT DETECTED	04/03/96 18:00	10 mg/L	CXVO	0.0005 mg/L
XYLENE, ORTHO-	NOT DETECTED	04/03/96 18:00	10 mg/L	CXVO	0.0005 mg/L
XYLENES (TOTAL)	NOT DETECTED	04/03/96 18:00	10 mg/L	CXVO	0.0005 mg/L
METHYL TERT-BUTYL ETHER	NOT DETECTED	04/03/96 18:00	•	CXVO	0.001 mg/L
TETRAHYDROFURAN	NOT DETECTED	04/03/96 18:00		CXVO	0.005 mg/L

By authority of PA 368 1978 as amended

Printed: 04/18/96 03:36:12

PAGE 02 (END OF REPORT)

## MICHIGAN DEPARTMENT OF PUBLIC HEALTH - Division of Laboratory Services Water Analysis Section - Lansing Laboratory

3500 M.L. King Jr. Lansing MI 48909

Laboratory report for sample: C96020270

System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE

City: ROCKFORD HI 49341

TWP-SEC/Key#:

County: KENT

RECEIVED

ATE #13/96

CXPT

RICHARD R JOHNSTON P.O. BOX 561 ROCKFORD HI 49341

WSSN/Pool# : 5730 Approved: SGK

Collected: 03/20/96 13:40 Entered: 03/22/96

Chlorinated: YES Sample unit:

Collector: RICHARD R JOHNSTON Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP Point description: 7 WELL#:

MAXIMUM DETECTION ANALYTE RESULT DATE TESTED CONTAMINANT LEVEL LIMIT ENDRIN [XPI] NOT DETECTED 03/22/96 08:00 0.002 mg/L CXPT 0.00001 mg/L 03/22/96 08:00 LINDANE (GAMMA-BHC) NOT DETECTED 0.0002 mg/L CXPT 0.00002 mg/L 03/22/96 08:00 CXPT 0.0001 mg/L KETHOXYCHLOR NOT DETECTED 0.04 mg/L **ALDRIN** NOT DETECTED 03/22/96 08:00 CXPT 0.001 mg/L 03/22/96 08:00 HEXACHLOROCYCLOHEXANE (ALPHA-BHC) CXPT 0.001 mg/L NOT DETECTED 03/22/96 08:00 HEXACHLOROCYCLOHEXANE (BETA-BHC) NOT DETECTED CXPT 0.001 mg/L HEXACHLOROCYCLOHEXANE (DELTA-BHC) 03/22/96 08:00 CXPT 0.001 mg/L NOT DETECTED CHLORDANE, alpha NOT DETECTED 03/22/96 08:00 0.002 mg/L CXPT 0.0002 mg/L 03/22/96 08:00 0.002 mg/L CHLORDANE, gamma-NOT DETECTED CXPT 0.0002 mg/L DDD,4,41-03/22/96 08:00 CXPT 0.001 mg/L NOT DETECTED DDE.4.4'-NOT DETECTED 03/22/96 08:00 CXPT 0.001 mg/L DDT,4,4'-03/22/96 08:00 0.001 mg/L NOT DETECTED CXPT ENDOSULFAN, alpha NOT DETECTED 03/22/96 08:00 CXPT 0.001 mg/L 03/22/96 08:00 CXPT ENDOSULFAN, beta NOT DETECTED 0.001 mg/L **ENDRIN ALDEHYDE** 03/22/96 08:00 CXPT NOT DETECTED 0.001 mg/L HEPTACHLOR NOT DETECTED 03/22/96 08:00 0.0004 mg/L CXPT 0.00004 mg/L HEPTACHLOR EPOXIDE NOT DETECTED 03/22/96 08:00 0.0002 mg/L CXPT 0.00002 mg/L 03/22/96 08:00 0.001 mg/L 0.0001 mg/L HEXACHLOROBENZENE NOT DETECTED CXPT 03/22/96 08:00 CXPT NOT DETECTED 0.05 mg/L 0.0001 mg/L HEXACHLOROCYCLOPENTADIENE 0.001 mg/L 03/22/96 08:00 OCTACHLOROCYCLOPENTENE NOT DETECTED CXPT 03/22/96 08:00 CXPT 0.001 mg/L POLYBROKINATED BIPHENYLS NOT DETECTED PCB (AROCLOR 1016) NOT DETECTED 03/22/96 08:00 0.0005 mg/L CXPT 0.0001 ng/L PCB (AROCLOR 1221) NOT DETECTED 03/22/96 08:00 0.0005 mg/L CXPT 0.0001 mg/L PCB (AROCLOR 1232) NOT DETECTED 03/22/96 08:00 0.0005 mg/L CXPT 0.0001 mg/L PCB (AROCLOR 1242) 03/22/96 08:00 0.0005 mg/L NOT DETECTED CXPT 0.0001 mg/L 03/22/96 08:00 PCB (AROCLOR 1248) NOT DETECTED 0.0005 mg/L CXPT 0.0001 mg/L PCB (AROCLOR 1254) NOT DETECTED 03/22/96 08:00 0.0005 mg/L CXPT 0.0001 mg/L PCB (AROCLOR 1260) NOT DETECTED 03/22/96 08:00 0.0005 mg/L CXPT 0.0001 mg/L DIELDRIN NOT DETECTED 03/22/96 08:00 0.001 mg/L CXPT 03/22/96 08:00 TOXAPHENE NOT DETECTED 0.003 mg/L CXPT 0.001 ma/L 03/22/96 08:00 BROHACIL NOT DETECTED CXPT 0.002 mg/L 03/22/96 08:00 CHLOROTHALONIL NOT DETECTED CXPT 0.001 mg/L DACTHAL NOT DETECTED 03/22/96 08:00 CXPT 0.001 mg/L TERBACIL NOT DETECTED 03/22/96 08:00 CXPT 0.002 mg/L 03/22/96 08:00 NOT DETECTED CXPT 0.001 mg/L **AMETRYN ALACHLOR** [YNP] NOT DETECTED 03/22/96 08:00 0.002 mg/L CXPT 0.0002 mg/L ATRAZINE NOT DETECTED 03/22/96 08:00 0.003 mg/L CXPT 0.0001 mg/L 03/22/96 08:00 CXPT NOT DETECTED 0.002 mg/L CYCLOATE NOT DETECTED 03/22/96 08:00 CXPT 0.002 mg/L BUTYLATE

By authority of PA 368 1978 as amended

Printed: 04/02/96 03:18:54

PAGE 01

(CONTINUED)

Laboratory report for sample : C96020270 System name/owner: CITY OF ROCKFORD

Collection address: 10 E BRIDGE

City: ROCKFORD HI 49341

TWP-SEC/Key#:

County: KENT

RICHARD R JOHNSTON P.O. BOX 561

ROCKFORD HI 49341

WSSN/Pool# : 5730

Approved: SGK

Collected: 03/20/96 13:40

Entered: 03/22/96

Chlorinated: YES Sample unit:

Collector: RICHARD R JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP

Point description: 7

WELL#:

Site:

ANALYTE	RESULT	DATE TESTED	MAXIHUM CONTAMINANT LEVEL	TEST	DETECTION LIHIT
CARBOXIN	NOT DETECTED	03/22/96 08:00		CXPT	0.002 mg/L
DIPHENAMID	NOT DETECTED	03/22/96 08:00		CXPT	0.001 mg/L
HEXAZINONE	NOT DETECTED	03/22/96 08:00		CXPT	0.003 mg/L
HETOLACHLOR	NOT DETECTED	03/22/96 08:00		CXPT	0.001 mg/L
METRIBUZIN	NOT DETECTED	03/22/96 08:00		CXPT	0.001 mg/L
PROMETON	NOT DETECTED	03/22/96 08:00		CXPT	0.001 mg/L
PRONAMIDE	NOT DETECTED	03/22/96 08:00		CXPT	0.001 mg/L
PROPAZINE	NOT DETECTED	03/22/96 08:00		CXPT	0.001 mg/L
SIMAZINE	NOT DETECTED	03/22/96 08:00	0.004 mg/L	CXPT	0.0001 mg/L
TEBUTHIURON	NOT DETECTED	03/22/96 08:00	••	CXPT	0.005 mg/L
BUTACHLOR	NOT DETECTED	03/22/96 08:00		CXPT	0.002 mg/L
PROPACHLOR	NOT DETECTED	03/22/96 08:00		CXPT	0.003 mg/L
CYANAZINE	NOT DETECTED	03/22/96 08:00		CXPT	0.001 mg/L
CYPRAZINE	NOT DETECTED	03/22/96 08:00		CXPT	0.001 mg/L
EPTAH	NOT DETECTED	03/22/96 08:00		CXPT	0.001 mg/L
TRIFLURALIN	NOT DETECTED	03/22/96 08:00		CXPT	0.001 mg/L

By authority of PA 368 1978 as amended

Printed: 04/02/96 03:18:54

PAGE 02 (END OF REPORT)

Laboratory report for sample: C96020269

System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE

City: ROCKFORD HI 49341

TWP-SEC/Key#:

County: KENT

PECEIVED ONTE UIS 195 CXHB

RICHARD R JOHNSTON P.O. BOX 561 ROCKFORD MI 49341 WSSN/Pool# : 5730 Approved: SGK

Collected: 03/20/96 13:35

Entered: 03/22/96

Chlorinated: YES

Sample unit:

Collector: RICHARD R JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP

Point description: 7

WELL#:

Site:

ANALYTE		RESULT	DATE TESTED	HAXIHUH CONTAMINANT LEVEL	TEST	DETECTION LIMIT
PICLORAM	[XHB]	NOT DETECTED	03/22/96 08:00	0.5 mg/L	CXHB	0.002 mg/L
BENTAZON		NOT DETECTED	03/22/96 08:00	_	CXHB	0.002 mg/L
2,4,5-T		NOT DETECTED	03/22/96 08:00		CXHB	0.001 mg/L
DINOSEB		NOT DETECTED	03/22/96 08:00	0.007 mg/L	CXHB	0.0003 mg/L
2,4,5-TP (SILVEX)		NOT DETECTED	03/22/96 08:00	0.05 mg/L	CXHB	0.0003 mg/L
ACIFLUORFEN		NOT DETECTED	03/22/96 08:00	•	CXHB	0.002 mg/L
DICAMBA		NOT DETECTED	03/22/96 08:00		CXHB	0.002 mg/L
2,4-D		NOT DETECTED	03/22/96 08:00	0.07 mg/L	CXHB	0.002 mg/L
PENTACHLOROPHENOL		NOT DETECTED	03/22/96 08:00	0.001 mg/L	CXHB	0.00006 mg/L

By authority of PA 368 1978 as amended

Printed: 04/04/96 03:38:26

PAGE 01 (END OF REPORT)

## MICHIGAN DEPARTMENT OF PUBLIC MEALTH - Division of Laboratory Services

Laboratory report for sample a 096020265

Bystem name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE ST

TWF-SEC/Key%:

County: KENT

MICHIGAN DEPARTMENT OF PUBLIC MEALTH - Division of Lab
Water Analysis Section - Lansing Laboratory
3500 M.L. King To Lansing MI 48909

Whener: CITY OF ROCKFORD
Idress: 10 E BRIDGE ST
City: ROCKFORD MI 49341

CITY: ROCKFORD MI 49341

Who
RICHARD R JOHNSTON

RICHARD R JOHNSTON P.O. BOX 561 ROCKFORD HI 49341

USSM/Poola : 5730 Approved: SGK

Collected: 03/20/96 13:30

Entered: 03/22/96

Chlorinated: YES

Sanale units

Collector: RICHARD R JOHNSYON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP

Point descriptions 7 WELL&:

Site:

AMALYTE		RESULT	DATE TESTED	NAXINUM CCHTAMINANT LEVEL	TEST	DEVECTION LIMIT
ALDICARB	EXLPI	NOT DETECTED	03/22/96 12:45		CXLP	0.0005 ma/L
ALDICARB SULFONE		NOT DETECTED	03/22/96 12:45		CXLP	0.0005 ng/L
ALDICARB SULFOXIDE		HOT DETECTED	03/22/96 12:45		CXLP	0.0005 Fig/L
PROFOXUR (BAYGON)		HOT DETECTED	03/22/96 12:45		DXLP	0.0002 mg/L
CARBARYL		HOT DETECTED	03/22/96 12:45		DXLP	0.0002 mg/L
CARBOFURAN		NOT DETECTED	03/22/96 12:45	0.04 mg/L	CXLP	0.0005 Aq/L
HETHICCARS		NOT DETECTED	03/22/96 12:45		CXLP	0.0002 ng/L
HETHONYL		NOT DETECTED	03/22/96 12:45		CXLP	0.0002 ng/L
űXA6YL		NOT PETESTED	03/22/96 12:45	0.2 mo/L	CXLP	0.002 me/L
HYOROXYCARBOFURAN. 3-		NOT DETECTED	03/22/96 12:45	•	CXLP	0.0062 Rg/L

Ev authority of PA 368 1978 as anended

Laboratory report for sample : 096020200

Eyster name/owners DITY OF ROCKFORD Collection address: 10 E BRIDGE

TUP-SEC/Xey%:

County: KENT

RICHARD R JOHNSTON
P.O. BOX 561

RECKFORD MI 49341

WSSh/Poal4 : 5730 Approved: UR

Collected: 03/20/96 13:45

Entered: 03/22/96

Chlorinated: YES

Sample unit: 32 Callector: RICHARD R JOHNSTON

Who callected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP


Point description: 7 WELL#:

Site:

ANALYTE	RESULT	DATE TESTED	HAXIMUH CONTAHINANT LEVEL	TEST	DETECTION LIMIT
MITRATE AS N (AUTOMATED)	1,3 mg/L	03/25/96 14:31	10 mg/L	CRA	0.2 md/l
MITRITE AS √ (AUTOHATED)	NOT DETECTED	03/ <b>2</b> 5/96 12: <b>46</b>	1 កក្/L	CRA	0.02 Ad/L
CHLGRIDE (AUTOMATED)	25 mg/L	03/25/96 14:18		URA	2 mg/L
FLUCRIDE (AUTOMATED)	0.9 Mg/L	03/25/96 12:46	4.0 mg/L	CRA	0.1 ag/L
HARDNESS AS CaCO3	159 ng/L	03/25/96 11:45		CRA	10 mg/L
ERON (AUTUMATED)	NOT DETECTED	03/25/96 11:45		CRA	0.1 mg/L
SULFATE (AUTCHATED)	57 mg/L	03/25/96 13:52		CRA	2 ng/L
SODIUM (AUTOMATED)	12 no/L	03/23/96 11:45		CRA	2 ac/C

By Euthority of PA 368 1978 as amended

Frinted: 03/26/96 03:20:25 PAGE 01 (END OF REPORT)



STATE OF MICHIGAN



JOHN ENGLER, Governor

## DEPARTMENT OF ENVIRONMENTAL QUALITY

HOLLISTER BUILDING, PO BOX 30473, LANSING MI 48909-7973

RUSSELL J. HARDING, Director July 5, 1996 REPLY TO:

DRINKING WATER & RADIOLOGICAL PROTECTION DIVISION 3423 N MARTIN L KING JR BLVD PO BOX 30830 LANSING MI 48909-8130

5730

Mr. Michael Young City of Rockford 7 South Monroe P.O. Box 561 Rockford, Michigan 49341-0561

Dear Mr. Young:

SUBJECT: Water Supply - Rockford

We have received the June 5, 1996, results from the Rockford Water Treatment Plant tap sample analyzed for limited organic compounds. The presence of atrazine was detected at 0.0002 mg/l in the CXPT test scan. This is well below the maximum contaminant level of 0.003 mg/l for this organic herbicide. When soil and climatic conditions are favorable, atrazine may get into drinking water by runoff into surface water or by leaching into ground water. We would like to do some follow up testing during the suspected high use period for this compound in 1997. A high use period would be during the spring application period and would likely be present during the spring runoff. We will provide the bottles and the use of the State of Michigan Laboratory at no cost to the city. The sampling can be coordinated with Mr. Richard Johnston and myself and will likely include some raw (untreated) water samples as well as some plant tap (finished) water samples. Until that time, we will continue to test for atrazine during the routine quarterly monitoring currently being performed on plant tap samples.

Should you have any questions, please call me.

Sincerely,

Brock F. Howard, P.E., District Engineer

Water Supply

Drinking Water and Radiological

**Protection Division** 

517-335-8317

BFH:lw

cc: City of Rockford, Attention: Mr. Richard Johnston, Plant Superintendent

Kent County Health Department

Elgar Brown

Laboratory report for sample : C96029811 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE City: ROCKFORD HI 49341

> TWP-SEC/Key#: County: KENT

RECEIVED

RICHARD R JOHNSTON P.O. BOX 561 ROCKFORD HI 49341

WSSN/Pool# : 5730 Approved: SGK

Collected: 06/04/96 15:10 Entered: 06/05/96

Chlorinated: YES Sample unit:

Collector: DICK JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP Point description: 7 WELL#:

Site:

ANALYTE	RESULT	DATE TESTED	MAXIMUM CONTAMINANT LEVEL	TEST	DETECTION LIMIT
ENDRIN EXPI	NOT DETECTED	06/05/96 10:00	0.002 mg/L	CXPT	0.00003 mg/L
LINDANE (GAMMA-BHC)	NOT DETECTED	06/05/96 10:00	0.0002 mg/L	CXPT	0.00002 mg/L
METHOXYCHLOR	NOT DETECTED	06/05/96 10:00	0.04 mg/L	CXPT	0.0001 mg/L
ALDRIN	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
HEXACHLOROCYCLOHEXANE (ALPHA-BHC)	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
HEXACHLOROCYCLOHEXANE (BETA-BHC)	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
HEXACHLOROCYCLOHEXANE (DELTA-BHC)	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
CHLORDANE,alpha	NOT DETECTED	06/05/96 10:00	0.002 mg/L	CXPT	0.0002 mg/L
CHLORDANE,ganna-	NOT DETECTED	06/05/96 10:00	0.002 mg/L	CXPT	0.0002 mg/L
DDD,4,49-	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
DDE,4,4'-	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
DDT,4,4°-	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
ENDOSULFAN,alpha	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
ENDOSULFAN,beta	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
ENDRIN ALDEHYDE	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
HEPTACHLOR	NOT DETECTED	06/05/96 10:00	0.0004 mg/L	CXPT	0.00004 mg/L
HEPTACHLOR EPOXIDE	NOT DETECTED	06/05/96 10:00	0.0002 mg/L	CXPT	0.00004 mg/L
HEXACHLOROBENZENE	NOT DETECTED	06/05/96 10:00	0.001 ag/L	CXPT	0.0001 mg/L
HEXACHLOROCYCLOPENTADIENE	NOT DETECTED	06/05/96 10:00	0.05 mg/L	CXPT	0.0002 mg/L
DCTACHLOROCYCLOPENTENE	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
OLYBROMINATED BIPHENYLS	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
PCB (AROCLOR 1016)	NOT DETECTED	06/05/96 10:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1221)	NOT DETECTED	06/05/96 10:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1232)	NOT DETECTED	06/05/96 10:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1242)	NOT DETECTED	06/05/96 10:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1248)	NOT DETECTED	06/05/96 10:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1254)	NOT DETECTED	06/05/96 10:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1260)	NOT DETECTED	06/05/96 10:00	0.0005 mg/L	CXPT	0.0001 mg/L
DIELDRIN	NOT DETECTED	06/05/96 10:00		CXPT	0.001 ng/L
TOXAPHENE	NOT DETECTED	06/05/96 10:00	0.003 mg/L	CXPT	0.001 mg/L
BROMACIL	NOT DETECTED	06/05/96 10:00		CXPT	0.002 mg/L
CHLOROTHALONIL	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
DACTHAL	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
TERBACIL	NOT DETECTED	06/05/96 10:00		CXPT	0.002 mg/L
AMETRYN	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
ALACHLOR EXNP.		06/05/96 10:00	0.002 mg/L	CXPT	
		06/05/96 10:00	-	CXPT	0.0002 mg/L
ATRAZINE CYCLOATE	0.0002 mg/L		0.003 mg/L		0.0002 mg/L
	HOT DETECTED	06/05/96 10:00		CXPT	0.002 mg/L
BUTYLATE	HOT DETECTED	06/05/96 10:00		CXPT	0.002 mg/L

By authority of PA 368 1978 as amended

Printed: 06/12/96 03:58:10

PAGE 01 (CONTINUED)

Laboratory report for sample : C96029811

System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE

City: ROCKFORD MI 49341

RICHARD R JOHNSTON

P.O. BOX 561 ROCKFORD MI 49341

TWP-SEC/Key#:

County: KENT

WSSN/Pool# : 5730 Approved: SGK

Collected: 06/04/96 15:10 Entered: 06/05/96

Chlorinated: YES Sample unit:

Collector: DICK JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP

Point description: 7

WELL#:

Site:

ANALYTE	RESULT	DATE TESTED	MAXIHUM CONTAMINANT LEVEL	TEST	DETECTION LIMIT
CARBOXIN	NOT DETECTED	06/05/96 10:00		СХРТ	0.002 mg/L
DIPHENAMID	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
HEXAZINONE	NOT DETECTED	06/05/96 10:00		CXPT	0.003 mg/L
METOLACHLOR	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/L
1ETRIBUZIN	NOT DETECTED	04/05/94 10:00		CXPT	0.001 mg/l
ROMETON	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/l
RONAHIDE	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/l
PROPAZINE	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/l
SIMAZINE	NOT DETECTED	06/05/96 10:00	0.004 mg/L	CXPT	0.0002 mg/l
EBUTHIURON	NOT DETECTED	06/05/96 10:00	J	CXPT	0.005 mg/l
UTACHLOR	NOT DETECTED	06/05/96 10:00		CXPT	0.002 mg/l
ROPACHLOR	NOT DETECTED	06/05/96 10:00		CXPT	0.003 mg/
YANAZINE	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/
YPRAZINE	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/l
PTAH	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/l
RIFLURALIN	NOT DETECTED	06/05/96 10:00		CXPT	0.001 mg/

By authority of PA 368 1978 as amended

Frinted: 06/12/96 03:58:10

PAGE 02 (END OF REPORT)

## MICHIGAN DEPARTMENT OF PUBLIC HEALTH - Division of Laboratory Services Water Analysis Section - Lansing Laboratory

3500 M.L. King Jr. Lansing MI 48909

Laboratory report for sample : C96029816 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE

City: ROCKFORD MI 49341

TWP-SEC/Key#: County: KENT



RICHARD R JOHNSTON P.O. BOX 561 ROCKFORD HI 49341

WSSN/Pool# : 5730 Approved: SGK Collected: 06/04/96 15:15

Entered: 06/05/96

Chlorinated: YES Sample unit:

Collector: DICK JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE HONITORING

Point codes (7) PRESSURE TANK/PLANT TAP

Point de⊲ ription: 7

WELL#:

Site:

ANALYTE		RESULT	DATE TESTED	HAXIMUM CONTAMINANT LEVEL	TEST	DETECTION LIHIT
PICLORAH	[XHB]	NOT DETECTED	06/05/96 08:00	0.5 mg/L	CXHB	0.002 mg/L
BENTAZON		NOT DETECTED	06/05/96 08:00		CXHB	0.002 mg/L
2,4,5-T		NOT DETECTED	06/05/96 08:00		CXHB	0.001 mg/L
DINOSEB		NOT DETECTED	06/05/96 08:00	0.007 mg/L	CXHB	0.0003 mg/L
2,4,5-TP (SILVEX)		NOT DETECTED	06/05/96 08:00	0.05 mg/L	CXHB	0.0003 mg/L
ACIFLUORFEN		NOT DETECTED	06/05/96 08:00	-	CXHB	0.002 mg/L
DICAMBA		NOT DETECTED	06/05/96 08:00		CXHB	0.002 mg/L
2,4-D		NOT DETECTED	06/05/96 08:00	0.07 mg/L	CXHB	0.002 Ag/L
PENTACHLOROPHENOL		NOT DETECTED	06/05/96 08:00	0.001 mg/L	CXHB	0.00006 mg/L

By authority of PA 368 1978 as amended

Printed: 06/11/96 04:39:56

(END OF REPORT) PAGE 01

Laboratory report for sample: C96029822 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE City: ROCKFORD MI 49341

TWP-SEC/Key#:

County: KENT

RECEIVED

RICHARD R JOHNSTON P.O. BOX 561 ROCKFORD HI 49341

WSSN/Pool# : 5730 Approved: SGK

Collected: 06/04/96 15:00 Entered: 06/05/96

Chlorinated: YES Sample unit:

Collector: DICK JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP

Point description: 7

₩ELL#:

Site:

				MAXIMUM		DETECTION
ANALYTE		RESULT	DATE TESTED	CONTAHINANT LEVEL	TEST	LIHIT
ALDICARB	[XLP]	NOT DETECTED	06/06/96 15:30		CXLP	0.0005 mg/i
ALDICARB SULFONE		NOT DETECTED	06/06/96 15:30		CXLP	0.0005 mg/m
ALDICARB SULFOXIDE		NOT DETECTED	06/06/96 15:30		CXLP	0.0005 mg/
PROPOXUR (BAYGON)		NOT DETECTED	06/06/96 15:30		CXLP	0.0002 mg/
CARBARYL		NOT DETECTED	06/06/96 15:30		CXLP	0.0002 Fig/
CARBOFURAN		NOT DETECTED	06/06/96 15:30	0.04 mg/L	CXLP	0.0005 mg/
ETH10CARB		NOT DETECTED	06/06/95 15:30	-	CXLP	0.0002 mg/
ETHOHYL		NOT DETECTED	06/06/96 15:30		CXLP	0.0002 mg/
JYKAXYL		NOT DETECTED	06/06/96 15:30	0.2 mg/L	CXLP	0.002 mg/l
YDROXYCARBOFURAN, 3-		NOT DETECTED	06/06/96 15:30	-	CXLP	0.0002 mg/

By authority of PA 368 1978 as amended

Printed : 06/18/96 04:26:13

PAGE 01 (END OF REPORT)

Laboratory report for sample : C96029883 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE City: ROCKFORD MI 49341

> TWP-SEC/Key#: County: KENT

> > RICHARD R JOHNSTON P.O. BOX 561

ROCKFORD HI 49341

RECEIVED ONTE DE 196

WSSM/Pool# : 5730 Approved: SGK

Collected: 05/04/96 15:00 Entered: 06/06/96

Chlorinated: YES Samole unit:

Collector: DICK JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP

Point description: 7

WELL#:

Sites

ANALYTE	RESULT	DATE TESTED	MAXIMUM CONTAHINANT LEVE	L TEST	DETECTION LIMIT	•
DIBROMOETHANE, 1,2 (XEV)  DIBROMO-3-CHLOROPROPANE, 1,2-	NOT DETECTED NOT DETECTED	06/23/96 13:00 06/23/96 13:00	0.00005 mg/L 0.0002 mg/L	CXEV CXEV	0.00003 mg/L 0.00005 mg/L	•
By authority of PA 368 1978 as amended		Printed : 0	6/27/96 04:26:59	PAGE 01	(END OF REPORT)	-

## HICHIGAN DEPARTMENT OF PUBLIC HEALTH - Division of Laboratory Services Water Analysis Section - Lansing Laboratory

3500 M.L. King Jr. Lansing MI 48909

Laboratory report for sample : C96032761 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE

BOX 561

City: ROCKFORD MI 49341

RICHARD R JOHNSTON

ROCKFORD HI 49341

TWP-SEC/Kay#:
County: KENT

RECEIVED

DATE 6/25/96 P

WSSN/Pool# : 5730 Approved: SGK

Collected: 06/17/96 13:30

Entered: 06/18/96

Chlorinated: YES Sample unit:

Collector: R JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE HONITORING

Point code: (7) PRESSURE TANK/PLANT TAP

Point description: PLANT TAP

WELL#:

Siter

ANALYTE	RESULT	DATE TESTED	HAXIHUM CONTAHINANT LEVEL	TEST	DETECTION
CHLOROACETIC ACID	NOT DETECTED	04/18/96 08:00		СХНА	0.001 mg/L
BROMOACETIC ACID	NOT DETECTED	06/18/96 08:00		CXHA	0.001 mg/l
DALAPON	NOT DETECTED	06/18/96 08:00	0.2 mg/L	CXHA	0.001 mg/i
DICHLOROACETIC ACID	0.042 mg/L	06/18/96 08:00	_	CXHA	0.001 mg/L
TRICHLOROACETIC ACID	0.007 mg/L	06/18/96 08:00		CXHA	0.001 mg/l
BROMOCHLOROACETIC ACID	0.008 mg/L	06/18/96 08:00		CXHA	0.001 mg/
DIBROMOACETIC ACID	0.001 mg/L	06/18/96 08:00		CXHA	0.001 mg/

By authority of PA 368 1978 as amended

Printed: 06/21/96 05:10:10

PAGE 01 (END

(END OF REPORT)

Laboratory report for sample : C96032841 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE City: ROCKFORD MI 49341

> TWP-SEC/Key#: County: KENT

RICHARD R JOHNSTON BOX 561 ROCKFORD HI 49341 RECEIVED

WSSN/Paol# : 5730 Approved: SGK

Collected: 06/17/96 13:30

Entered: 06/19/96

Chlorinated: YES Sample unit:

Collector: R JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP
Point description: PLANT TAP WELL#:

Site:

ANALYTE RESULT DATE TESTED CONTAMINANT LEVEL TEST LIMIT

/ ENDOTHALL NOT DETECTED 06/24/96 13:00 0.1 mg/L CXEN 0.01 mg/L

By authority of PA 368 1978 as amended Printed: 06/26/96 05:32:33 PAGE 01 (END OF REPORT)

Laboratory report for sample: C96032830 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE City: ROCKFORD MI 49341

TWP-SEC/Key#:

County: KENT

RICHARD R JOHNSTON BOX 561

ROCKFORD MI 49341

RECEIVED JUN 2 7 1996

₩SSN/Pool# : 5730

Approved: SGK

Collected: 06/17/96 13:30

Entered: 06/19/96

Chlorinated: YES Sample unit:

Collector: R JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE HONITORING

Point code: (7) PRESSURE TANK/PLANT TAP

Point description: PLANT TAP WELL#:

Site:

MUNIXAM DETECTION RESULT ANALYTE DATE TESTED CONTAMINANT LEVEL TEST LIMIT 0.02 mg/L CXDQ NOT DETECTED 06/20/96 10:30 . .....

By authority of PA 368 1978 as amended

Printed: 04/25/96 04:17:50 PAGE 01 (END OF REPORT)

Laboratory report for sample : C96043170 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE City: ROCKFORD HI 49341

TWP-SEC/Key#:

County: KENT



RICHARD R JOHNSTON BOX 561 ROCKFORD HI 49341

WSSN/Pool# : 5730 Approved: SGK

Collected: 08/19/96 16:00 Entered: 08/26/96

Chlorinated: YES Sample unit:

Collector: DICK JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING Point code: (7) PRESSURE TANK/PLANT TAP

Point description: PLANT TAP WELL#:

Site:

ANALYTE	RESULT	DATE TESTED	MAXIHUM CONTAHINANT LEVEL	TEST	FIRIT DETECTION
- ENDRIN	NOT DETECTED	08/21/96 08:00	0.002 mg/L	CXPT	0.00003 mg/L
- LINDANE (GAMMA-BHC)	NOT DETECTED	08/21/96 08:00	0.0002 mg/L	CXPT	0.00002 mg/L
- HETHOXYCHLOR	NOT DETECTED	08/21/96 08:00	0.04 mg/L	CXPT	0.0001 mg/L
ALDRIN	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
HEXACHLOROCYCLOHEXANE (ALPHA-BHC)	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
HEXACHLOROCYCLOHEXANE (BETA-BHC)	NOT DETECTED	08/21/96 08:00		CXPT	0.0 <b>01</b> mg/L
HEXACHLOROCYCLOHEXANE (DELTA-BHC)	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
- CHLORDANE, alpha	NOT DETECTED	08/21/96 08:00	0.002 mg/L	CXPT	0.0002 mg/L
- CHLORDANE, gamma-	NOT DETECTED	08/21/96 08:00	0.002 mg/L	CXPT	0.0002 mg/L
DDD,4,4'-	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
DDE,4,4?-	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
DDT,4,4'-	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
ENDOSULFAN,a1pha	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mo/L
ENDOSULFAN,beta	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
- ENDRIN ALDEHYDE	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
~ HEPTACHLOR	NOT DETECTED	08/21/96 08:00	0.0004 mg/L	CXPT	0.00004 mg/L
- HEPTACHLOR EPOXIDE	NOT DETECTED	08/21/96 08:00	0.0002 mg/L	CXPT	0.00004 na/L
- HEXACHLOROBENZENE	NOT DETECTED	08/21/96 08:00	0.001 mg/L	CXPT	0.0001 mg/L
- HEXACHLOROCYCLOPENTADIENE	NOT DETECTED	08/21/96 08:00	0.05 mg/L	CXPT	0.0002 mg/L
OCTACHLOROCYCLOPENTENE	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
- POLYBROMINATED BIPHENYLS	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
PCB (AROCLOR 1016)	NOT DETECTED	08/21/96 08:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1221)	NOT DETECTED	08/21/96 08:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1232)	NOT DETECTED	08/21/96 08:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1242)	HOT DETECTED	08/21/96 08:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1248)	NOT DETECTED	08/21/96 08:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1254)	NOT DETECTED	08/21/96 08:00	0.0005 mg/L	CXPT	0.0001 mg/L
PCB (AROCLOR 1260)	NOT DETECTED	08/21/96 08:00	0.0005 mg/L	CXPT	0.0001 mg/L
DIELDRIN	NOT DETECTED	08/21/96 08:00		CXPT	0.001 ma/L
- TOXAPHENE	NOT DETECTED	08/21/96 08:00	0.003 mg/L	CXPT	0.001 mg/L
BROMACIL	NOT DETECTED	08/21/96 08:00		CXPT	0.002 mg/L
CHLOROTHALONIL	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
DACTHAL	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
TERBACIL	NOT DETECTED	08/21/96 0 <b>8:00</b>		CXPT	0.002 mg/L
AMETRYN	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
ALACHLOR EXNP3	NOT DETECTED	08/21/96 08:00	0.002 mg/L	CXPT	0.0002 ng/L
- ATRAZINE	NOT DETECTED	08/21/96 08: <b>0</b> 0	0.003 mg/L	CXPT	0.0002 mg/L
CYCLOATE	NOT DETECTED	08/21/96 08:00		CXPT	0.002 mg/L
BUTYLATE	NOT DETECTED	08/21/96 08:00		CXPT	0.002 mg/L
→ ATRAZINE CYCLOATE	NOT DETECTED NOT DETECTED	08/21/96 08: <b>0</b> 0 08/21/96 08:00	_	CXPT CXPT	0.0002 mg/l 0.002 mg/l

Laboratory report for sample : C96043170 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE

City: ROCKFORD MI 49341

BOX 561

RICHARD R JOHNSTON

ROCKFORD MI 49341

TWP-SEC/Key#:

County: KENT

WSSN/Pool# : 5730 Approved: SGK

Collected: 08/19/96 16:00 Entered: 08/26/96

Chlorinated: YES Sample unit:

Collector: DICK JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP Point description: PLANT TAP WELL4:

Site:

ANALYTE	RESULT	DATE TESTED	MAXIMUM CONTAMINANT LEVEL	TEST	DETECTION LIMIT
CARBOXIN	NOT DETECTED	08/21/96 08:00		CXPT	0.002 mg/L
DIPHENAMID	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/L
HEXAZINONE	NOT DETECTED	08/21/96 08:00		CXPT	0.003 ma/L
HETOLACHLOR	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/l
HETRIBUZIN	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/l
PROMETON	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/l
PRONAMIDE	NOT DETECTED	08/21/96 08:00		CXPT	0.001 ma/!
PROPAZINE	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/
SIHAZINE	NOT DETECTED	08/21/96 08:00	0.004 mg/L	CXPT	0.0002 mg/l
TEBUTHIURON	NOT DETECTED	08/21/96 08:00		CXPT	0.005 mg/l
BUTACHLOR	HOT DETECTED	08/21/96 08:00		CXPT	0.002 ma/l
PROPACHLOR	NOT DETECTED	08/21/96 08:00		CXPT	0.003 mg/
CYANAZINE	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/
CYPRAZINE	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/
EPTAH	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/i
TRIFLURALIN	NOT DETECTED	08/21/96 08:00		CXPT	0.001 mg/

By authority of PA 368 1978 as amended

Printed: 09/04/96 02:03:14

PAGE 02 (END OF REPORT)

Laboratory report for sample : 096043171 System mame/owners CITY OF ROCKFORD

Collection address: 10 E BRIDGE

City: ROCKFORD NI 49341

TWP-SEC/Key∲i

County: KEHT

BECEINED

RICHARD R JOHNSTON

90% 561

ROCKFORD HI 49341

USSN/Pool≢ : 5730

Approved: SGK

Collected: 08/19/96 16:00

Entered: 08/26/96

Chiorinated: YES

Sample unit:

Collector: DICK JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANY TAP

Point description: PLANT TAP WELL#:

Site:

AMALITE	RESULT	DATE TESTED	MAXINUM CONTAMINANT LEVEL	TEST	DETECTION LIXIT
T PICLORAM	NOT DETECTED	08/21/94 08:00	0.5 mg/L	CXHB	0.002 mg/L
BENTAZON	NOT DETECTED	08/21/96 08:00		CXHB	0.001 mg/L
3,4,5-7	NOT DEVECTED	08/21/96 08:00		CXHB	0.001 mg/L
-DINOSER	MOT DETECTED	08/21/94 <b>08:00</b>	0.007 mg/L	CXHB	0.0002 ag/L
· 2,4,5-TP (SILVEX)	NOT DETECTED	08/21/94 08:00	0.05 mg/L	CXHB	0.0002 mg/L
ACIFLUORFER	HOT DETECTED	03/21/96 08:00		CXHB	0.001 mg/L
Divansa	HOT DETECTED	08/21/96 08: <b>00</b>		CXHB	0.001 mg/L
- 2,4-3	WOT DETECTED	08/21/95 08: <b>00</b>	0.07 ng/L	CXHB	0.001 ng/L
PENTACHLORGPHENOL	NOT DETECTED	08/21/96 08:00	0.001 mg/L	CXHB	0.00006 ma/L

By authority of FA 368 1972 as amended

Laboratory report for sample : C96043164 System name/owner: CITY OF ROCKFORD Collection address: 10 E BRIDGE

City: ROCKFORD MI 49341

TWF-SEC/Key#: County: KENT

RECEIVED DATE 8/30/96

RICHARD R JOHNSTON

BOX 561

ROCKFORD HI 49341

WSSN/Pool# : 5730

Approved: SGK

Collected: 08/19/96 16:00

Entered: 08/26/96

Chlorinated: YES

Sample unit:

Collector: DICK JOHNSTON

Who collected: (1) PUBLIC SUPPLY OPERATOR

Source: (1) TYPE I

Purpose: (0) ROUTINE MONITORING

Point code: (7) PRESSURE TANK/PLANT TAP

Point description: PLANT TAP WELL#: F

Site:


ANALYTE	RESULT	DATE TESTED	MAXIMUM CONTAMINANT LEVEL	TEST	DETECTION LIMIT
AL BECAND		A0 /0A /0/ 00-00			A AAAC 4
ALDICARB	NOT DETECTED	08/20/96 22:29		CXLP	0.0005 mg/L
ALDICARB SULFONE	NOT DETECTED	08/20/96 22:29		CXLP	0.0005 mg/L
ALDICARB SULFOXIDE	NOT DETECTED	08/20/96 22:29		CXLP	0.0005 mg/L
FROPOXUR (BAYGON)	NOT DETECTED	08/20/96 22:29		CXLP	0.001 mg/L
CARBARYL	NOT DETECTED	08/20/96 22:29		CXLP	0.001 mg/L
- CARBOFURAN	NOT DETECTED	08/20/96 22:29	0.04 mg/L	CXLP	0.0005 mg/L
METHIOCARB	NOT DETECTED	08/20/96 22:29	-	CXLP	0.001 mg/L
METHOMYL	NOT DETECTED	08/20/96 22:29		CXLP	0.001 mg/L
- OXAMYL	NOT DETECTED	08/20/96 22:29	0.2 mg/L	CXLP	0.001 mg/L
HYDROXYCARBOFURAN, 3-	NOT DETECTED	08/20/96 22:29	-	CXLP	0.001 mg/L

By authority of PA 368 1978 as amended

Printed: 08/27/96 03:54:00

PAGE 01 (END OF REPORT)

## City of Rockford



W E



## CITY OF ROCKFORD

Steve J. Jazwiec, Mayor Michael F. Young, City Manager

PO Box 561

Rockford, Michigan

49341-0561 T 616-866-1537 ^ F 616-866-6406

www.rockford.mi.us

November 14, 2011

Blake Krueger, CEO Wolverine World Wide 9341 Courtland Drive Rockford MI 49351

#### Dear Blake:

We, the Rockford City Council, feel it important to write to you to express our support to Wolverine World Wide (WWW), as you work through redevelopment of the tannery complex in downtown Rockford. We have monitored this process since it was announced several years ago that WWW would be closing down the tannery. We appreciate the close relationship your staff has with the City's staff, not only on this project, but historically on the various issues that face both of our organizations. The commitment to our community by WWW is unparalleled and it is clear that your contribution to the City of Rockford and the region as a whole has helped make us one of the more desirable locations in the State of Michigan.

We have recently had the opportunity to review the EPA petition submitted by Ms. McIntosh, Ms. Mancewicz, and Mr. Medich. We are deeply concerned and disappointed by the tone of the petition. The petition is short on facts; long on emotion: and rife with questionable accusations. We have received frequent updates from the City Manager and staff during the pre-demolition phase and demolition itself. We know that staff completed daily inspections of the site and have found WWW to be in compliance with the permit conditions placed on this project. It should also be noted that an overwhelming majority of the public supports the efforts of WWW and the redevelopment of this property and it is clear that the accusations made by a small group of individuals are not reflective of the community as a whole. We would also like to compliment WWW on the recent public meeting you held, which gave the community at large an opportunity to hear directly from WWW on the redevelopment efforts. From all indications, the initial round of testing looks promising and we are anxiously awaiting the results of your continued monitoring of the property. We are currently communicating with the DEQ and EPA officials through City staff to provide factual information from our perspective on the redevelopment process and also to address the inaccuracies found throughout the petition.

Blake Krueger, CEO November 14, 2011 Page two

We appreciate the continued support of WWW and want you to know that you have ours. Thank you again for all of your efforts.

Sincerely,

CITY OF ROCKFORD

Steve Jazwiec, Mayor

Brien Dews, Mayor Pro-tem

Mary Eadie, Council Member

Richard P. Moll, Council Member

Jerry Coon, Council Member